

1st year maintenance

51

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/W - Const ⁿ of Road from Nalard Road to madheli Banpatola under survey (gen). N/A - Mohammad Salam Alam Agg. no - 08/SB/D/2020-21 Actual comp dt - 27/06/22					

① Restoration of Rein cuts

1	6x	5.0x	0.30x	0.30x	= 2.7 m ³
	10x	20x	0.30x	0.30x	= 18.0 m ³
	2x	2.8x	0.90x	0.30x	= 47512 m ³
					$\Sigma = 25.45 \text{ m}^3$
					Limit $\Sigma = 25.31 \text{ m}^3$

② mending up of Berms/shoulder stripping excess soil.

	8x	10.0x	0.30x		= 24 m ³
	4x	30x	0.16x		= 22 m ³
	7x	2.10x	0.90x		= 44.73 m ³
					$\Sigma = 140.73 \text{ m}^3$
					Limit $\Sigma = 140.63 \text{ m}^3$

③/15.10 maint. of Road sign.

$\Sigma = 0.05 \text{ km}$

④/15.11) maint. of 20m x 1m sign $\Sigma = 0.06 \text{ km}$

[Signature]
05/09/23

SE

[Signature]
05/09/23

. 1st year measur.
Abstract of Cost.

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(1) Restoration of Paints dry side rooms no-51 Qr 25.31 m ³ @ 386.28/m ³ = 9777.00					
(2) making up of Bams/shutter strips excess work dry side rooms no-51 Qr 140.63 m ³ @ 57.53/m ³ = 8096.00					
(3/5.7) making of sign board dry side rooms no-51 Qr 0.05 km @ 1078.34/km = 54.00					
(4/5.4) met. of 200 m ² km stone dry side rooms no-51 Qr 0.06 km @ 628.44/km = 38.00 total = 17,965.00					
Add 12% W.S. = 2156.00					
10% S.Fee = 886.00					
1% L.Cost = 180.00					
total = 21,187.00					

[Signature]
 05/09/23
 JK

[Signature]
 05/09/23

Material statement: -

Qr = 25.31 m³ @ 35.01

[Signature]
 05/09/23