

KRISHNAPALI CONST. PVT. LTD.

MMGSY-SC KATHAR

Schedule XLV-Form No. 134

DALAN PMGSY ROAD BHAWARA PUL TO
RAILWAY GUMATI.

R. U. D KATHAR DIVISION

HASANGAR / KATHAR SUB-DIVISION

P. B. No-2133

MEASUREMENT BOOK

Situation of work—

Agency by which work is executed—

Date of measurement—

No. and date of agreement.

(These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work—					
Bhawara pu to railway bumph					
Agency—					
Krishna Paley Const. Pvt. Ltd.					
Agreement No—					
Date of Work Order—					
Date of Completion—					

(1) Restoration of retaining

$6 \times 4.05 \times 2.50 \times 0.30 =$	18.22
$1 \times 4.00 \times 3.30 \times 0.30 =$	3.96
$7 \times 4.97 \times 1.95 \times 0.30 =$	20.35
$6 \times 8.00 \times 2.00 \times 0.30 =$	28.80
$7 \times 3.80 \times 1.50 \times 0.15 =$	5.98
$4 \times 4.80 \times 1.20 \times 0.15 =$	3.45
$6 \times 5.32 \times 1.32 \times 0.15 =$	6.32
	$= 87.08 m^3$

(2) making up of berms/

Shoulder:

$2 \times 26.00 \times 1.20 =$	62.40
$2 \times 25.00 \times 1.50 =$	75.00

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
VTH YEAR 2 - (M)					
Abstract cost - (M)					
(1) Restoration of rainfalls.					
vide cost. page no - 1					
87.08 m ³ @ 365.25 / m ³				=	31806.00
(2) making up berms / shoulder.					
vide cost. page no - 2					
798.74 m ² @ 54.16 / m ²				=	43260.00
(3) Repair of pot holes lined					
75 mm					
vide cost. page no - 2					
100.77 m ³ @ 302.40 / m ³				=	30473.00
(4) patch repair over ^{bitumen} pot					
holes surface on.					
vide cost. page no - 2					
100.75 m ² @ 204.68 / m ²				=	20622.00
(5) maint. of H.P. Culverts.					
vide cost. page no - 3					
4.00 nos @ 1131.64 / nos				=	4527.00
(6) maint. of Blah Culvert.					
vide cost. page no - 3					
1.00 NO @ 2336.81 / NO				=	2337.00

Continuation

