

~~Rajput R.C.D Road to Sundani (Fokra)~~

Schedule XLV-Form No. 134

Sankar Bore Road to Sati Pur Bihuan,

Hyder

DIVISION

MMSY (NDB)

~~MSY~~ 218311

SUB-DIVISION

RBA construction

MEASUREMENT BOOK

1615

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
5 maintenance of Road					
Sign					Qty = 0.18K
6 mgn of 200m					
Post					Qty = 0.28K
7 Trimming of grass and weed					
4 x 4 x 1.5					= 24 m ²
					Qty = 20 m ²
					6.3 m ²
Ram					
05/07/25					
J.E					

Abstract of Cost

N/W - Sonham Bank road to
Sripur Bahadur

Agency - RBA Wastha

Ag. No - SBA 08/2023-24

D.O.S - 19.07.23

D.O.C - 18.07.24

1 Restoration of Rim
of Soil

Qty = 63.572 m³ vide

TMB P.O-34

466.17 Rs = 296352

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
2/ Maintenance of contour Shoulder					
Qty =	489.68 m ²		vide TMB		
			P.W. - 35		
		@ 65.57	Rs =	32108 =	
3/ Path repair over S.M.					
Qty =	32.81 m ²		vide TMB		
			P.W. - 35		
		@ 392.39	Rs =	12874 =	
4/ Maintenance of C.D.					
Qty =	6 NO		vide TMB	P.W.	
		@ 1529.28	Rs =	9175 =	
5/ Maintenance of Road S.M.					
Qty =	0.18 kg		vide TMB		
			P.W. 36		
		@ 1406	Rs =	253 =	
6/ Maintenance of 200 m Stone					
Qty =	0.22 kg		vide TMB		
			P.W. 36		
		@ 778.90	Rs =	168 =	
7/ Trimming of Grass f Weeds					
Qty =	20 m ²		vide TMB	P.W.	
	6.3	@ 3.19	= 36	20	
			Rs =	84215 =	

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
					BF B = 84215 = ∞
Add 18% W.S.T				(+)	15159 = ∞
Add 1% L.C				(+)	843 = ∞
S.F				(+)	505 = ∞
					<u>100722 = ∞</u>
10 % below w) Per Br (-)					10672 = ∞
					<u>RS = 90650 = ∞</u>
Ranish 05/07/25 J.E					Jankpal <u>10/08/28</u>