

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग कार्य प्रमंडल, बेनीपट्टी।

दिनांक 14.08.25

पत्रांक 1397

प्रेषक, कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, बेनीपट्टी।

सेवा में,
अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव,
बिहार ग्रामीण पथ विकास अभिकरण,
ग्रामीण कार्य विभाग,
बिहार, पटना।


विषय:- शीर्ष NEW MAINTENANCE POLICY - 2018 (MR - 3054) में आवंटन उपलब्ध कराने के संबंध में।

महाशय,
उपरोक्त विषय के संबंध में कहना है शीर्ष NEW MAINTENANCE POLICY - 2018 (MR-3054) अन्तर्गत पथ में संलग्न विवरणी के अनुसार आवंटन उपलब्ध कराने की कृपा की जाय ताकि संवेदक का भुगतान किया जा सके।

अनु०:-

1. अध्याचना प्रमाण पत्र 1 पृष्ठ में।
2. उपयोगिता प्रमाण पत्र एक प्रति।

विश्वासभाजन,


09.08.25

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, बेनीपट्टी।

09.08.25

FORM GFR 19-A

(See Government of India's Decision (I) below Rule-150)
Form of Utilisation Certificate Upto the month of 31 July 2025

New Maintenance policy - 2018

PJU - Executive Engineer, R.W.D (W) Division, Benipatti

Sl. No	Name of Schemes	Sanction No. & Date with Amount (In Rs. lacs)	Amount Received (In Rs. lacs)	Particulars
1	Construction of Rural roads under New maintenance policy - 2018	Authorization letter No. 59 we dt-16.07.2025 Rs.193.02146 Lakh	5369.02239	Certified that out of Rs. 5369.02239 Lakh received during the years up to 2025-26 (31 July 2025) in favour of Ex. Engineer, RWD (W) Division Benipatti, Madhubani, Bihar, a sum of Rs. 5165.34018 Lakh has been utilized for the purpose of New maintenance policy-2018 as given in the margin for which the balance of Rs 203.68221 Lakh remaining unutilized at the end of the period under.

2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.


Kind of Checks exercised:-

- Works have been supervised by Executive Engineer/Superintending Engineer.
- Periodical inspection has been conducted by Executive Engineer/Superintending Engineer.
- Construction materials have been tested.
- Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/Executive Engineer.
- All other codal formalities have been observed.

3. Physical Progress achieved:-

- Construction of Road Works.
- Construction of CD Works.


Divisional Account Officer,
R.W.D (W) Division
Benipatti


Executive Engineer
R.W.D (W) Division
Benipatti


09-08-25

Format of Requisition under Head New Maintenance policy - 2018 (MR- 3054) for the month of August-2025

Name of Division :- Benipatti

Sl. No.	Project No.	Name of work	Project ID no (per MTS)	Name Of Contractor	Administrative Approval (NA) Letter No & Date	Administrative Approval (NA)		Agreement Amount (in Lakh)		Agreement No & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of BBO (in lakh)	Thickness of Bitumen Layer (in mm)	Value of Material Consumed in Percentage	Percentage Total Allocated Agreement (in Lakh)	up-to-date expenditure as per MTS (in Lakh)	Requisition against work done (in Lakh)	Remarks
						Length (in km)	Amount of (in lakh)	Initial Rectification with Surface Removal (in Lakh)	5 Year Residue Maintenance (in Lakh)										
1	1	2	3	4	5	7	8	9	10	11	12	13	14	15	16	17	18	19	20
1	RAJMA/BEN/24/0002	LD42-703 TO BALA INTHARWA (TRACK42)	31910001111	Ashishch Kumar	1086/ 01.08.2024	2.730	166.92000	111.72707	20.58762	D/MRD/2024/25 27.07.2024	26.08.2025	10.07.2025	2735.00	25	5	0.00000	0.00000	129.25682	Work Completed
Total						2.730	166.92000	111.72707	20.58762	—	—	—	2735.00	25	5	0.00000	0.00000	129.25682	

Divisional Engineer,
R.W.D.C.D., Benipatti



 Divisional Engineer
 R.W.D.C.D., Benipatti
 09.08.25

OFFICE OF THE EXECUTIVE ENGINEER
RWD WORKS DIVISION
BENIPATTI

Name of Scheme:- L042-T03 TO BALA INTCHARWA (TRACK42), Package No. - RM/MA/BEN/24/0005

Project ID – 31910002113


Certified that all item wise 100%
measurement has been taken by
me


10/07/25
Junior Engineer
RWD Work Section Bisfi
Works Division Benipatti

Certified that all item wise 50%
measurement has been Cheked by
me



10.07.25
Assistant Engineer
RWD Work Sub Division Bisfi
Works Division Benipatti

Certified that all item wise 10%
measurement has been Cheked by
me


10.07.25
Executive Engineer
RWD Works Division
Benipatti

Road Name:-L042-T03 to Bala Intharwa(track-42) Contractor Name:- Abhishek Kumar


Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI.TEGORY mm/km ROAD	Latitude	Longitude	Event
$Y = 0 * X^2 + 0.816 * X + 249$										
9/7/25	11:20:1	59	0.1	320	0	3200	2996 G	26.634001	85.985046	Normal
9/7/25	11:20:55	59	0.1	360	10.1	3600	3421 G	26.634745	85.985262	Normal
9/7/25	11:21:36	59	0.1	300	20.2	3000	2894 G	26.635474	85.985401	Normal
9/7/25	11:22:11	59	0.1	320	10.1	3200	2981 G	26.636449	85.985483	Normal
9/7/25	11:22:58	59	0.1	250	20.2	2500	2389 G	26.637028	85.985756	Normal
9/7/25	11:23:12	59	0.1	310	20.2	3100	2912 G	26.637440	85.985984	Normal
9/7/25	11:23:56	59	0.1	320	10.1	3200	3126 G	26.638052	85.986452	Curve
9/7/25	11:24:05	59	0.1	340	10.1	3400	3259 G	26.638464	85.986832	Normal
9/7/25	11:24:58	59	0.1	260	10.1	2600	2459 G	26.638722	85.987451	Speed Breaker
9/7/25	11:25:7	59	0.1	250	10.1	2500	2456 G	26.639060	85.988050	Normal
9/7/25	11:25:52	59	0.1	290	10.1	2900	2812 G	26.639522	85.989501	Normal
9/7/25	11:26:10	59	0.1	290	10.1	2900	2848 G	26.640341	85.989851	Normal
9/7/25	11:27:0	59	0.1	310	20.2	3100	2945 G	26.640636	85.990098	Normal
9/7/25	11:27:57	59	0.1	240	20.2	2400	2207 G	26.641718	85.990502	Normal
9/7/25	11:27:17	59	0.1	310	20.2	3100	2778 G	26.642131	85.989844	Normal
9/7/25	11:28:0	59	0.1	350	10.1	3500	3318 G	26.643411	85.990316	Normal
9/7/25	11:28:53	59	0.1	370	10.1	3700	3452 G	26.644750	85.990715	Normal
9/7/25	11:29:14	59	0.1	230	10.1	2300	2125 G	26.645534	85.991031	Normal
9/7/25	11:29:59	59	0.1	220	20.2	2200	2044 G	26.645681	85.992161	Normal
9/7/25	11:30:24	59	0.1	290	10.1	2900	2796 G	26.645956	85.992187	Normal
9/7/25	11:31:0	59	0.1	280	20.2	2800	2533 G	26.647087	85.992408	Normal
9/7/25	11:31:0	59	0.1	210	10.1	3000	2654 G	26.648269	85.992450	Normal
9/7/25	11:32:0	59	0.1	270	10.1	2700	2452 G	26.649085	85.992548	Normal
9/7/25	11:32:59	59	0.1	260	10.1	2600	2370 G	26.649853	85.992896	Normal
9/7/25	11:33:51	59	0.1	300	20.2	3000	2696 G	26.650913	85.993600	Normal
9/7/25	11:34:36	59	0.1	280	10.1	2800	2612 G	26.651519	85.993891	Normal
9/7/25	11:35:11	59	0.1	250	20.2	2500	2288 G	26.652631	85.994356	Normal
9/7/25	11:36:0	59	0.1	310	20.2	3100	2784 G	26.653178	85.994815	Normal
9/7/25	11:37:21	59	0.03	310	20.2	3100	2784 G	26.653178	85.994815	Normal
			Length	2.73						

 10/07/25
 10.07.25
 A. E.

 10.07.25

File :D:\bump report\abhishek\2304202514.Xls, Section No. :59, Eqn :test

Name of Customer :Abhishek Kumar, Name of Work/ Road :L042-T03 To Bala Intharwa, Lab Job number :



AB
10/07/25
SE.

Am
10.07.25
A-E

AB
10.07.25

1st on A/C Bill.

21

Sch. XI.V—Form No. 134

Particulars	Details of actual measurement				Contents of item
	No.	L.	B.	D.	
Name of work -					and Rep of
Road from					2042 - 70310
Bala Imtharwa under					
Hanlakou. BLOCK.					
Name of contractor -					Shri Abhishek Kr.
Agst no -					06/MBD/2024-25
Date of start -					
Date of comp -					
Actual Date of comp -					
1/1 Clearing and grubbing					
Road Land.					
Qty vide TPOB Form - ①					
1.092 Hect (100 ft) 1.09					
@ Rs 76926.08					= Rs 83849.00
2/2 Dismantling of existing str.					
Like culvert brick m					
Qty vide TPOB Form 10 Item ①					
30.69 m ³ @ Rs 321.93					= Rs 9880.00
3/3 Dismantling of existing str.					
Like culvert brick m					
Qty vide TPOB Form 10 Item ①					

Continuation

Continuation