

रंजय कुमार (खुदगो) द्वारा
सिंधी मढिया रोड से मिमराही (कै)

mmgsy (sc)

Schedule XLV Form No. 134.

Executive Engineer, R.W.D. DIVISION
Tehra

Assistant Engineer, R.W.D. SUB-DIVISION
Konch.

Measurement Book

926

रंजय कुमार (खुदगो)

2nd year maintenance

Bill

69

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of Road, Cont. Impact of Road from					
Singhara Mathiya					
Road to Almorchi					
Under MMGSY (SC)					
Agency: Sanjay Kumar					
Agg. No - 21/585/2021/22					
MMGSY					
Date of Commencement - 10.08.2021					
Date of Completion - 09.08.2022					
Date of Actual Completion - 13.08.23					

measurement -

(1) Restoration of
rain culverts
do do

$$8 \times 10 \times 1.10 \times 0.30 = 26.40 \text{ m}^3$$

$$6 \times 15.0 \times 1.05 \times 0.30 = 28.35 \text{ m}^3$$

$$10 \times 18.0 \times 0.90 \times 0.30 = 48.60 \text{ m}^3$$

$$5 \times 21.0 \times 0.95 \times 0.30 = 29.92 \text{ m}^3$$

$$8 \times 0.50 \times 1.00 \times 0.30 = 1.20 \text{ m}^3$$

$$7 \times 0.60 \times 1.00 \times 0.30 = 1.26 \text{ m}^3$$

$$\text{Total} = 157.39 \text{ m}^3$$

(2) Making up Bumps

Continuation



ABSTRACT of Cost

74

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(1) Restoration of Rain culs/Bams do do 157.39m ³ Qty m ³ Page (69) @ ₹ 409.06/m ³ ₹ 63595.00					
(2) Making up Bams/ Shoulder do do 887.20 m ² Qty Turb Page no (70) @ ₹ 60.28/m ² ₹ 53480.00					
(3) Repair of Pot holes filled with 75mm do do 0.37 m ³ Qty Turb Page (70) @ ₹ 8952.29/m ³ ₹ 3312.00					
(4) Patch repair over Pot holes with 20mm Breux Carpet & Seal Coat do do 123.33 m ² Qty Turb Page (70) @ ₹ 234.98/m ² ₹ 28980.00 C.O ₹ = 149367.00					

Continuation



