

ପରୀକ୍ଷା ଆୟତନ - ଆକାଶ ଓ ପୃଷ୍ଠା

ଶିକ୍ଷା ଓ ଶିଳ୍ପ ବିଭାଗ

Schedule XLV-Form No. 134

ଅନୁସନ୍ଧାନ ଆୟତନ - ବିଭାଗୀୟ ଶିକ୍ଷା

ଅନୁସନ୍ଧାନ ବିଭାଗ

ବିଭାଗ ଓ ବିଭାଗ

DIVISION

ଅନୁସନ୍ଧାନ ବିଭାଗ

Scheme:- MHC.S.Y[SC]

A.C. R.W.D. SUB-DIVISION
Bachha

Measurement Book

No:- 3709

3709

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>3rd year Maintenance</u>					
<u>Name of work:- Const. of mainte.</u>					
<u>of road from Tahirpur</u>					
<u>to Yadav tola Kurni</u>					
<u>to la Itwa Loha tal under</u>					
<u>MCHSY(S.C)</u>					
<u>Agency:- Mithlesh Kumar</u>					
<u>Vill - Bhagwanpur</u>					
<u>P.S. - Awatar Nagar,</u>					
<u>Dist - Chapra</u>					
<u>Agg. No.:- 07/S&D/20-21</u>					
<u>Date of comm:- 08-07-2020</u>					
<u>Date of Actual completion:- 15-4-22</u>					

① Restoration of sained					
--- etc.					
	5	9.6	0.95	0.30	13.68 m ³
	7	14.5	0.85	0.30	34.80 m ³
	4	20.8	0.70	0.30	17.47 m ³
	6	18.0	0.85	0.30	27.54 m ³
	5	17.5	0.75	0.30	19.68 m ³
	4	15.0	0.95	0.30	17.10 m ³
	2	20.5	0.85	0.30	10.45 m ³
	6	13.5	0.75	0.30	22.0 m ³
	3	19.0	0.90	0.30	15.39 m ³
					174.33 m ³
② Making up of Berms					
Shoulder etc. ---					
	4	18.0	0.95		68.4 m ²

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	2	30.0	0.90		54.0m ²
	6	30.0	0.95		171.0m ²
	3	30.0	1.10		99.0m ²
	5	30.0	0.90		135.0m ²
	4	25.0	1.10		110.0m ²
	2	30.0	0.90		54.0m ²
	2	18.5	0.95		35.15m ²
					726.55m ²

③ Repair of pot holes etc.

2	5.5	0.9	0.075		0.74m ³
2	4.8	0.9	0.075		0.64m ³
1	5.25	0.85	0.075		0.33m ³
2	4.5	0.85	0.075		0.57m ³
1	6.2	0.90	0.075		0.42m ³
1	7.0	0.90	0.075		0.47m ³
1	6.8	0.85	0.075		0.43m ³
2	6.2	0.90	0.075		0.83m ³
1	5.9	0.90	0.075		0.39m ³
1	6.5	0.9	0.075		0.43m ³
2	8.5	0.9	0.075		1.14m ³
1	6.3	0.9	0.075		0.42m ³
1	7.5	0.9	0.075		0.50m ³
2	5.8	0.9	0.075		0.78m ³
2	7.2	0.9	0.075		0.97m ³
					9.06m ³

④ Patch repair over pot hole w/ 20mm premix do. do.

4	6.30	0.95			23.94m ²
2	18.3	1.10			40.26m ²

Continuation

64.2m²

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>ABSTRACT OF COST</u>					
① Restoration of rainwater etc.					
Qty. vide TMB P. No. (82)					
174.33 m ² @ Rs 386.14/m ² = Rs					67316.00
② Making up of Berms/ Shoulder etc					
Qty. vide TMB P. No. (83)					
726.55 m ² @ Rs 57.36/m ² = Rs					41675.00
③ Repair pot holes do do					
Qty. vide TMB P. No. (83)					
9.06 m ³ @ Rs 12246.83/m ³ = Rs					110956.00
④ Patch repair over pot holes with 20mm Primis do do					
Qty. vide TMB P. No. (84)					
120.63 m ² @ Rs 338.43/m ² = Rs					40825.00
⑤ Patch repair over bituminous surface do do					
Qty. vide TMB P. No. 84					
120.63 m ² @ Rs 350.23/m ² = Rs					42248.00
⑥ Maintenance of C/D work (Slab culvert)					
Qty. vide TMB P. No. (84)					
02 nos @ Rs 2329.20/each = Rs					4658.00
					= Rs 307678.00

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	

Continuation