

MM54 2005/11 Const of Road from Mithlakhet near

Schedule XLV-Form No. 134

Notice to govt. Tak in Area of Block

(5) 2005-01/171- 18/5/577 (Bikram Kumar)

Agreement No. 42581/MS54-22-23 DIVISION

(ARERA Block)

Const. Act. 11461046 -
Main. Act. 2310880 -
To be: 13771926 -

SUB-DIVISION

MB NO - 2806

MEASUREMENT BOOK

Date of Commencement. 18/6/22

Date of Completion 17/6/23

1st Year Maintenance

45

Sch.XLV-Form No. 134

[illegible]

Continuation

$$1 \times 8.0 \times 1.0 \times 0.3 = 2.40$$

ABSTRACT OF COST.

48

Sch.XLV-Form No. 134

Particulars	Details of actual measure				Contents of area
	No.	L.	B.	D.	
1. Restoration of rain water					
			171		
	165.44/m ²			P-45	
	@ 404.26/m ²			B. 66,848=-	
2. Maintenance of Berms					
1 shoulder. - - E/A					
	459.56 m ²			P-46	
	@ 60.48/m ²			Rs. 27,794=-	
3. Patch repair over					
BT surface. - - E/A					
	108.74 m ²			P-46	
	@ 284.76/m ²			Rs. 30,965=-	
4. Maintenance of Hume					
pipe culvert. - - E/A					
1 No.				P-47	
	@ 1166.58/No.			Rs. 1167=-	
5. Maintenance of slab					
culvert. - - E/A					
1 No.				P-47	
	@ 2394.96/No.			Rs. 2395=-	
6. Maintenance of road					
sign. - - E/A					
	0.16 Km			P-47	
	@ 1104.58/Km			Rs. 177=-	

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measure				Contents of area
	No.	L.	B.	D.	
			128	6148	211
Less below		3.86%	(-)		5721
				128	142,490

①
24375
28

Material Statement

soil -	193 m ³
Coarse sand	0.65 m ³
Stone Chips -	3.26 m ³
Reluon -	0.190 M-T.

①
24375
28