

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
4.iii) Patch repair over pot-					
153 holes with 20 mm premix					
Surfacing materials					
8x19.0 x 0.152		22.80	m ²		
9x16.0 x 0.302		43.20	m ²		
10x12.0 x 0.452		54.00	m ²		
9x13.0 x 0.152		17.0	53.00		
5x4.0 x 0.152		3.00	m ²		
		140.55	M ²		
$\frac{5}{7}$ Maints to C/S work (H. Pavement)					
		3.15			
$\frac{6}{9}$ Maints to Road 80cm		0.225			
$\frac{7}{10}$ Maints to 200 M 2 x 4 Stone		0.36	KM		
$\frac{8}{11}$ Cutting of branches of Trees		3.15			
$\frac{9}{11}$ Cutting of shrubs from Roadways		15.15			
$\frac{10}{12}$ Whitewashing of parapet walls					
Red work 2 tree trunks					
Top 3x2x6.15 x 0.40		14.76	m ²		
End Parapet 2x4x0.40x1.20		5.76	m ²		
Inner Side 3x2x6.15x0.60		22.14	m ²		
		42.66	m ²		

On 25/11/25
JE

Side
Contd. 25/11/25
AE

5th 7a Main Road
ABSTRACTS OF COST

31

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1. Restoration of Roadcut					
Qty side PNO 29 in TM3					
		81.10	703		
@ 3522 21/M ³					R 285292
2. Making up A Bump					
Shawlex					
Qty side PNO 29 in TM3					
		506.10	0 M ²		
@ 512711 M ²					R 261702
3. Repair of Pot holes filled					
SS with 75mm WBM 1:2:5					
Qty side PNO 29 in TM3					
		140.55	0 M ²		
@ 199273 M ²					R 280722
4. Patch repair over pot					
holes with 20mm premix					
Surfacing Materials					
Qty side PNO 30 in TM3					
		140.55	0 M ²		
@ 259242 M ²					R 3646120
5. Maintenance of H.P. Culvert					
Qty side PNO 30 in TM3					
		343			
@ 1104235 PNO					R 33132
6. Maintenance of Road Sign					
Qty side PNO 30 in TM3					
@ 225 KM @ 1067244/KM					R 2402
Total R					1227852

Continuation

Continuation