

Take to United States Court

14-16757-5C

MBN 6-1521

Schedule XLV-Form No. 134

MBN 6-1521

DIVISION

by

MBN 6-1521

SUB-DIVISION

O

MEASUREMENT BOOK

Abstract of cost

85

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Item No (1) Restoration of Ram					
Cuts Berms with soil mason					
etc - do - do - etc					
Qty vide TMBP-81					
73.188 m ³ @ ₹ 104.06/m ³ - ₹					29572.00
Item No (2) Making up of Berms/					
Shoulder Stripper excess to					
Soil from the Shoulder					
Surface to achieve level					
etc - do - do -					
Qty vide TMBP-82 - ₹					
397.10 m ² @ ₹ 60.28/m ² - ₹					23937.00
Item No (3) Repair of Pot holes					
filled with 75mm thick					
BM - do - do - etc					
Qty vide TMBP-82					
133.413 m ² @ ₹ 10441.96/m ² - ₹					26168.00
2.506 m ³					
Item No (4) Patch Repair					
over Pot holes with					
mpe Seal Surface					
Qty vide TMBP-83					
33.413 m ² @ ₹ 256.86/m ² - ₹					8582.00

Continuation

C.O. ₹ 88259.00

10/10/25