

5th year maintenance

79

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of Road:-	Sanghaili				
	Tendua path to				
	mokersi dalit Jala				
Agency:-	Ajay Kumar mishra				
Agreement no-	11SB/2019-20				
Actual date of comp-	08-10-20				
Date of entry:-	19-11-25				

1. Restoration of Raincude:-

2 X	6 X	1.00 X	0.30	=	3.60
2 X	2 X	1.00 X	0.30	=	1.20
1 X	4 X	1.15 X	0.30	=	1.38
2 X	3 X	0.90 X	0.30	=	1.62
1 X	2.5 X	0.85 X	0.30	=	0.63
2 X	6 X	1.15 X	0.30	=	4.14
2 X	3 X	1.00 X	0.30	=	1.80
2 X	1.5 X	0.90 X	0.30	=	0.81
1 X	7 X	1.10 X	0.30	=	2.31
2 X	4 X	0.90 X	0.30	=	2.16
2 X	3 X	1.15 X	0.30	=	2.07
1 X	3.5 X	1.00 X	0.30	=	1.05
Qty -					22.77 m ³

② Maintenance of E/shoulder:-

2 X	15 X	1.125	=	33.75
2 X	8.50 X	1.10	=	18.70
2 X	6.80 X	0.90	=	12.24
2 X	11 X	1.125	=	24.75

Continuation

~~1911125 A6~~ ~~1911-25 SE~~

1/ Restoration of Palm rule

obj	vide	p.no -	79
-----	------	--------	----

22-77/m@	230.58	Re	-	8666.00
----------	--------	----	---	---------

② Maintenance of E/shoulder -

City wide page no- 30

455.36 m^2 (C)	58.37	R8	-	26579.20
-------------------------	-------	----	---	----------

③ $\frac{3}{2}$ Repair of pot holes with

width 75 mm

Sl. No. Page no. 80

29.28'	(a)	385.63	28	-	11283.00
--------	-----	--------	----	---	----------

④/s Repair of pot holes with mss -

Sl. no page no - (80)

29.08/12	247.82	R8	-	72.56.20
----------	--------	----	---	----------

Continuation

material statement.

Emulsion	- 0.039 m ⁵
Biterminous	- 0.22 m ⁵
Aggregate	- 1.94 m ³
Earthwork	- 22.71 m ³

~~Jan~~
19-11-25
J.E