

Meggsy sc

MB No: 3481

Schedule XLV-Form No. 134

~~સરકારી ગામ સ્થાનક ગામજોડામાં વાવવાની જે
જમીનની જમીન કુલ કમીટી - ૨૧૦૬ મેટર~~

~~સરકાર - ૨૧૦૬ મેટર ૧૨૪૪૧~~

~~સરકાર :- બીજાની~~ SUB-DIVISION

MB No: 3481

Measurement Book

3481

2nd Year maintenance

37

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/m :- Maintenance Construction of road from Dewaliya to Mishramuliya Haze Huge Kahi Chowk Han Under mossy (SC) at Block off Talabpur Agency:- Sri Dheeraj Kr. Mishra Agreement no:- D.O.C :- 26.11.2022					
(1) Restoration of rainCutts/ berms with Soil ————					
1x 2.00m x 0.80m x 0.30m = 6.72 m³					
2x 15.00m x 0.80m x 0.30m = 10.80m³					
2x 12.00m x 0.80m x 0.30m = 5.76m³					
2x 2x 8.00m x 0.80m x 0.30m = 7.68m³					
2x 6.00m x 0.80m x 0.30m = 2.88m³					
2x 3.00m x 0.80m x 0.30m = 1.44m³					
					35.28 v
(2) making up of berms/ Shoulder , —————					
2x 2x 25.00m x 0.80m = 80.00					
2x 2x 20.00m x 0.80m = 64.00					
2x 9.00m x 0.80m = 14.40m					
2x 3.00m x 0.80m = 4.80m					
					163.20v

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
③ Patch repair over					
pot holes with —					
3 x 1.50m		x 1.00m			= 4.50 m ²
6 x 0.80m		x 0.80m			= 3.84 m ²
3 x 2.00m		x 1.50m			= 13.50 m ²
2 x 2.40m		x 1.25m			= 6.00 m ²
2 x 1.20m		x 1.10m			= 2.64 m ²
					<u>30.48 m²</u>
Limit Qty. = 30.47 m ²					
④ Patch repair over					
bituminous surface —					
Qty. same as 1.00 :- ③					
					= 30.47 m ²
⑤ maintenance of road					
sign —					
					= 0.80 km
⑥ maintenance of					
200m and Km Stones					
					= 0.14 km
⑦ Cutting of branches					
of trees and shrubs					
					= 2 nos.
⑧ Cutting of shrubs					
from roadway					
					= 7 nos.
⑨ Trimming of grass					
and weeds —					
					= 3.85 m ²

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
⑩ maintenance of trees by the road side —					
— 39 nos					
⑪					
⑫					
⑬					
⑭					
⑮					
⑯					
⑰					
⑱					
⑲					
⑳					
㉑					
㉒					
㉓					
㉔					
㉕					
㉖					
㉗					
㉘					
㉙					
㉚					
㉛					
㉜					
㉝					
㉞					
㉟					
㊱					
㊲					
㊳					
㊴					
㊵					
㊶					
㊷					
㊸					
㊹					
㊺					
㊻					
㊼					
㊽					
㊾					
㊿					

ABSTRACT OF COST

40

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Restoration of raincuts/berms with soil					
Qty. vide TMSF (37)					
1. no :- ① = 35.22 m^3					
@ Rs 386 = 14 / m^3					Rs 13623 = 00
② making up of berms/Shoulder					
Qty. vide TMSF (37)					
1. no :- ② = 163.20 m^2					
@ Rs 57 = 36 / m^2					Rs 9361 = 00
③ Patch repair over pot holes with					
Qty. vide TMSF (38)					
1. no :- ③ = 30.47 m^2					
@ Rs 335 = 88 / m^2					Rs 10234 = 00
④ Patch repair over bituminous surface					
Qty. vide TMSF (38)					
1. no :- ④ = 30.47 m^2					
@ Rs 348 = 82 / m^2					Rs 10629 = 00
⑤ maintenance of road sign					
Qty. vide TMSF (38)					
1. no :- ⑤ = 0.60 km					
@ Rs 1077 = 82 / km					Rs 862 = 00
					Rs 44709 = 00

Continuation

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
					0.11 m 66876 = 0.0
Add 12% GST (+)					0.025 = 0.0
Add 1% L.Cess (+)					0.069 = 0.0
Add S.Fee					0.0208 = 0.0
					75778 = 0.0
Sagib					
26.11.25					
S.E.					

Material Statement

Earth = 50.94 m³Crushed Stone chips = 2.01 m³

Bitumen = 0.065 mT

Sagib

26.11.25

S.E.

Sagib

26.11.25

A.E.

Balance (S-90) = 1.094 mT.

1st Year = (-) 0.024 mT

2nd Year = (-) 0.048 mT

3rd Year = (-) 0.065 mT

Balance (S-90) = 0.957 mT

Sagib

26.11.25

S.E.

Continuation

Sagib

26.11.25

A.E.