कार्यपालक अभियंता का कार्यालय ग्रामीण कार्य विभाग कार्य प्रमण्डल, बाँका-2

पत्रांक 3218 (अनु)/बाँका

दिनांक 13 12 2625

प्रेषक,

कार्यपालक अभियंता ग्रामीण कार्य विभाग, कार्य प्रमण्डल, बाँका–2

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी—सह—सचिव बिहार ग्रामीण पथ विकास अभिकरण, पटना।

विषय:- शीर्ष 4515 मुख्यमंत्री ग्रामीण सड़क उन्नयन योजना (RRSMP-GEN) के अन्तर्गत विभिन्न पथों के कार्यों के भुगतान हेतु निधि की अधियाचना के संबंध में।

महाशय,

उपर्युक्त विषयक मुख्यमंत्री ग्रामीण सड़क उन्नयन योजना (RRSMP-GEN) के अन्तर्गत विभिन्न पथों के भुगतान हेतू 20651768/- की अधियाचना विहित प्रपत्र में तैयार कर आपके आवश्यक कार्यवाई हेतू समर्पित की जाती है ।

अनु0 :- 1. विहित प्रपत्र में आवंटन की मांग।

2. उपयोगिता प्रमाण पत्र।

3. मापी पुस्त की छाया प्रति।

विश्वासभाजन

ग्रंप्र,कार्यपालक अभियंता ग्राठका०वि०,कार्य प्रमंडल

बाँका-2

GFR 12-B

[See Rule 256 (2)]

FORM OF UTILIZATION CERTIFICATE

- (2) Certified that I have satisfied myself that the conditions on which the loan was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was actually spent for the purpose for which the loan was made.

Kinds of checks exercised

1.Allotment

2. MB

3.Cash book

Signature....

Designation Executive Engineer R.W.D(W) Division, Banka-2

Date.- 11.12.2025

Var	ne of the Wo	rks Division	-Banka 2	F	Requisitio	n Forma	t for Sc	heme I	имс	SUY/RRS	MP (Genera	al)				1	
SI. No.	Package No.	Project ID as per MIS	Name of Road	AA Length (in km.)	Administrative Approval (construction work) Amount (in Lakh)	Agreement (construction		Date of Completion as per Agreement	Actual Date of Compl etion	Work Status (WBM/WMM/B M/SDBC etc.)	Value of IRI (in mm/ km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content (in %)	Total Previous Allotted Amount (in Lakh)	Upto date Expenditure as per MIS (in Lakh)	Value of Work Done (in Lakh)	Current Demand (in Lakh)	Remarks
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	RRSMP/24-25 Banka-2/02	3070360350211	Sarocha To Basletwa	2.000	96.659	81.23004	12CMBD/20 25-26 19.06.25	18.06.26	-	Surface Completed	2552	25mm	5%	32.27898	32.27898	46.95078	14.67180	Work in process
2	RRSMP/24-25 Banka-2/02	3070360350228	Bhagalpur Dumka Road To Kora Bandha	2.690	150.745	121.30290	12CMBD/20 25-26 19.06.25	18.06.26		Surface Completed	2594	25mm	5%	34.41398	34.41398	64.75418	30.34020	Work in process
3	RRSMP/24-25 Banka-2/02	3070360350212	L105-RAJDAH TO BELTIKARI (TRACK105)	2.000	101.925	82.88642	12CMBD/20 25-26 19.06.25	18.06.26		Surface Completed	2575	25mm	5%	22.04719	22.04719	44.34148	22.29429	Work in process
4	RRSMP/24-25 Banka-2/02	3070360350224	L111-L063 BHALJOR DAM RD TO BAGHWA (TRACK111)	2.500	129.375	105.41083	12CMBD/20 25-26 19.06.25	18.06.26	,	PCC in Progress	2442	25mm	5%	4.86844	4.86844	24.00715	19.13871	Work in process
5	RRSMP/24-25 Banka-2/02	3070360350239	RCD Link Road To Habitation Panda Toia	0.450	18.284	16.81535	12CMBD/20 25-26 19.06.25	18.06.26	•	Surface Completed	2418	25mm	5%	3.33664	3.33664	13.34657	10.00993	Work in process
6	RRSMP/24-25 Banka-2/02	3070360350225	L112-LABANDO RD VIA BHALUA BADAR TO HALMATTA (TRACK112)	3.400	192.978	160,17402	12CMBD/20 25-26 19.06.25	18.06.26		PCC in Progress	2385	25mm	5%	4.09636	4.09636	22.95022	18.85386	Work in process
7	RRSMP/24-25 Banka-2/02	3070360350219	Repair of road from Papharni (Mandar Parwat) Madhusudan Bhagwan Mandir	2.975	231.440	201.60320	2CMBD/20 25-26 19.06.25	18.06.26	-	Surface Completed	2495	25mm	5%	26.48547	26.48547	105.94188	79.45641	Work in process
8	RRSMP/24-25 Banka-2/02	3070360350226	Bhagalpur Dumka Road To Hechla	1,420	63,712	54.91937	2CMBD/20 25-26 19.06.25	18.06.26	-	Surface Completed	2490	25mm	5%	26.52174	26.52174	38.27422	11.75248	Work in process
			Total														206.51768	11

It is certified that Physical & Financial Progress has been updated in MIS.

RWD, Works Division Banka-2

Note:

1 Above Signed Copy along with Forwading Letter & Utilisation Certificate must be uploaded in MIS.

2 Signed Hard Copy and Soft Copy (in excell) of recorded IRI is enclosed (As Applicable).

अधियाचना हेतु प्रमाण-पत्र

प्रमाणित किया जाता है कि **... ९, १८९** योजनान्तर्गत

- 1. पथ / पुल Repair of Road from Papharni में कराये गये (Mandal Parwat To Madhusudan Bhagwar Mondir कार्य की गुणवत्ता जांच की गयी है जो निर्धारित मानक / विशिष्टियों के अनुरूप है।
- 2. अद्यतन कराये गये कार्य की मापी संबंधित मापी पुस्तिका में दर्ज है जिसका सत्यापन कर लिया गया है।

कनीय अभियता यामीण कार्य विभाग कार्य प्रशाखा देविभाग

सहायक अभियंता ग्रामीण कार्य विभाग कार्य अवर प्रमण्डल.

कार्यपालक अभियंता ग्रामीण कार्य विभाग कार्य प्रमण्डल बाँका-2 Name: Repair of road from Papharni (Mandar Parwat) Madhusudan Bhagwan Mandir, Contractor Name : Prince Construction

				Cont	ractor N	ame : Prin	ce Cons	Iruction		HICKOCO SAN		
1	Time	Section	Length	Bumps	Speed	OR	IRI	CATEGORY	Latitude	1.ongitude	Event	
		No.	in km	in mm	Rate	mm/km	mm/km	ROAD				
10/25	12:20:23	50	0.1	230	30.3	2300	2442	G	24.82995	87.03521	Normal	Y = 0 * X ^ 2 + 0.954 * X = 247.7
10/25	12:20:33	50	0.1	210	30.4	2100	2251	G	24.82924	87.03464	Normal	x = 3100
10/25	12:20:47	50	0.1	300	30.3	3000	3110	G	24.82857	87.03404	Curve	Y = 3205
10/25	12:20:56	50	0.1	220	30.3	2200	2347	G	24.82785	87.03427	Normal	
10/25	12:21:04	50	0.1	240	30.4	2400	2537	G	24.827	87.03459	Normal	
10/25	12:21:13	50	0.1	230	30.4	2300	2442	G	24.82615	87.03486	Normal	(R) RURAL ROAD
10/25	12:21:25	50	0.1	210	30.3	2100	2251	G	24.82523	87.03505	Normal	Good Average Poor
10/25	12:21:30	50	0.1	190	30.2	1900	2060	G	24.8243	87.03489	Normal	<4000 4001-5000 >5001
/ 10/ 25	12:21:39	50	0.1	210	30.1	2100	2251	G	24.82351	87.03456	Normal	
/ 10/ 25	12:21:57	50	0.1	240	30.1	2400	2537	G	24.82207	87.03403	Normal	
10/25	12:22:23	50	0.1	220	30.2	2200	2347	G	24.82128	87.03353	Normal	
10/25	12:22:39	50	0.1	250	30.2	2500	2633	G	24.82046	87.03313	Normal	
10/25	12:22:57	50	0.1	230	30.2	2300	2442	G	24.81959	87.03284	Normal	
10/25	12:23:18	50	0.1	240	30.3	2400	2537	G	24.81876	87.03249	Normal	
/ 10/ 25	12:23:37	50	0.1	210	30.3	2100	2251	G	24.81803	87.03192	Normal	
10/25	12:24:23	50	0.1	200	30.3	2000	2156	G	24.81729	87.03132	Normal	
/ 10/ 25	12:24:39	50	0.1	310	30.4	3100	3205	G	24.81649	87.03128	Curve	
10/25	12:24:57	50	0.1	220	30.4	2200	2347	G	24.81565	87.03168	Normal	
/ 10/ 25	12:25:18	50	0.1	250	30.3	2500	2633	G	24.81474	87.03173	Normal	
/ 10/ 25	12:25:37	50	0.1	220	30.2	2200	2347	G	24.81382	87.03172	Normal	
/ 10/ 25	12:25:50	50	0.1	260	30.1	2600	2728	G	24.81294	87.03169	Normal	
/ 10/ 25	12:26:07	50	0.1	230	30.1	2300	2442	G	24.81206	87.03138	Normal	
0/ 10/ 25	12:26:25	50	0.1	250	30.2	2500	2633	G	24.81121	87.03107	Normal	
0/10/25	12:26:40		0.1	210	30.4	2100	2251	G	24.81035	87.0308	Normal	
0/10/25	12:26:59	-	0.1	220	30.3	2200	2347	G	24.80949	87.03059	Normal	
0/ 10/ 25	-		0.1	260	30.2	2600	2728	G	24.80858	87.03043	Normal	
0/10/25		-		240	30.1	2400	2537	7 G	24.80768	87.03035	Normal	
0/10/25		-		220	30.2	2200	2347	7 G	24.80679		Normal	
10. 20	12.20.01	-		-		2100	2204		24 80606	87 02993	Curve	

29-16-25

30.3

310

0.1

2.9

Rural Works Department Works Section, Bounsi-- 61

50

Length -

20/10/25

12:28:19

Assistant Engineer Rural Works Department Works Sub-Division, Bounsi

3100

Average -

87.02993

24.80606

G


3205

2495

Rural Works Department Works Division, Banka-2

Executive Engineer 30 -10 - 35

Curve



29/10/25 3B,

89-10-25 AF

A de 200-10-5