

Warendpur silv mandir to kamoshish
yadav ke ghar Tal.

पिपडा - 30 मीटर 20.42.21-7

Schedule XLV Form No. 134.

RRSMP

EXECUTIVE ENGINEER

RURAL WORKS DEPARTMENT

WORKS DIVISION SIWAN-2

DIVISION

ए. ए. ए. 21, 22, 23, 24, 25, 26

SUB-DIVISION

RRSMP

Measurement Book

1085

2nd / final BM!

8

Sch. XLV-Form No. 134

[illegible]

(1/8) Cost of granular sub-base - 100
 actual depth $\left[\frac{5+4.5+3.25}{3} \right] \times 3.25 \times 100 = 8.533 \text{ m}^3$

(2/10) P.V and Laying masonry - 3
 $8 \times \left(\frac{5+4.5+3.25}{3} \right) \times 3.25 \times 0.025 = 0.40 \text{ m}^3$

(3/8) Cost of subgrade and shoulder
 $2 \times 3 \times 30 \times 1.50 \times 0.30 = 81 \text{ m}^3$
 $2 \times 1 \times 30 \times 0.50 \times 0.30 = 9 \text{ m}^3$
 $= 90 \text{ m}^3$

Continuation

ABSTRACT of Cost

10

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(1/1) Cleaning and Grubbing					
Qty. returned No (1)					
0.15 ha @ 73248.35/ha					10987 =
(2/4) Excavation for Rd -					
Way cutting de -					
Qty. returned No (1)					
79.749 m ³ @ 9597/m ³					7573 =
(3/2) Compn of subgrade/					
shoulder de -					
Qty. returned No 4, 8					
450 m ³ @ 243.83/m ³					109723 =
(4/8) Compn of Granular					
sub-base - de -					
Qty. returned No (4)					
52.533 m ³ @ 2432.77/m ³					137965 =
(5/10) Placed laying m ² 300					
Grade - de -					
Qty. returned No 4, 8					
43-151 m ² @ 4899.03/m ²					211398 =
(6/12) Compn un-reinforced					
concrete de -					
Qty. returned No (4)					
913.649 m ³ @ 2455.35/m ³					2338363 =
(7/30) Placed fixing logs					
Board de -					
Qty. returned No (3)					
870 m ² @ 4872.66/m ²					42618 =

Total 2867627 =

Continuation

Continuation