

Tamilce & Agem (sc)

sc

# Schedule XLV-Form No. 134

Name of work :- Jalad Tola Bishampur to To T

Agency :- Tanwar Alam.


RIGID KIRGAGAGF-1 DIVISION

Form No - 174/11111/930/2020-21.

R. CO. D Kachadhambas SUB-DIVISION

3062

MEASUREMENT BOOK



# 2nd yr. Maintenance Bill.

88

Sch. XLV—Form No. 134

| Particulars                                                  | Details of actual measurement |        |        |       | Contents of area     |
|--------------------------------------------------------------|-------------------------------|--------|--------|-------|----------------------|
|                                                              | No.                           | L.     | B.     | D.    |                      |
| N/W:- Construction of Road from Jalal Tola Bishanpur to T07. |                               |        |        |       |                      |
| Agency- Tanweer Alam Kishanganj                              |                               |        |        |       |                      |
| Agst No- 174/MMGSY/SB30/2020-21                              |                               |        |        |       |                      |
|                                                              |                               |        |        |       |                      |
|                                                              |                               |        |        |       |                      |
|                                                              |                               |        |        |       |                      |
| (1) Restoration of Rain Cuts — E/I.                          |                               |        |        |       |                      |
|                                                              | 1x                            | 20.0x  | 1.75x  | 0.30= | 15.75 m <sup>3</sup> |
|                                                              | 1x                            | 27.50x | 1.90x  | 0.30= | 15.67 m <sup>3</sup> |
|                                                              | 1x                            | 10.0x  | 0.900x | 0.30= | 2.7 m <sup>3</sup>   |
|                                                              | 1x                            | 25.50x | 1.10x  | 0.30= | 8.41 m <sup>2</sup>  |
|                                                              | 1x                            | 30.00x | 1.05x  | 0.30= | 9.45 m <sup>3</sup>  |
|                                                              | 1x                            | 11.20x | 0.850x | 0.30= | 2.86 m <sup>2</sup>  |
|                                                              | 1x                            | 10.0x  | 0.900x | 0.30= | 2.7 m <sup>3</sup>   |
|                                                              |                               |        |        | Qty=  | 57.54 m <sup>3</sup> |
| (2) Maintenance of earthen shoulder — E/I.                   |                               |        |        |       |                      |
|                                                              | 1x                            | 30.0x  | 1.25   | =     | 37.5 m <sup>2</sup>  |
|                                                              | 1x                            | 28.75x | 1.15   | =     | 33.06 m <sup>2</sup> |
|                                                              | 1x                            | 15.50x | 1.30   | =     | 20.15 m <sup>2</sup> |
|                                                              | 1x                            | 30.0x  | 1.50   | =     | 45.00 m <sup>2</sup> |
|                                                              | 2x                            | 30.0x  | 1.35   | =     | 81.00 m <sup>2</sup> |
|                                                              | 10x                           | 10.0x  | 1.00   | =     | 100.00               |

Continuation Qty = 316.71 m<sup>2</sup>

| Particulars           | Details of actual measurement |        |                |            | Contents of area |
|-----------------------|-------------------------------|--------|----------------|------------|------------------|
|                       | No.                           | L.     | B.             | D.         |                  |
|                       |                               |        | BIF            | $P_3 = 1,$ | 13,603.00        |
| Add 12% GST           | (+)                           |        |                | $P_3 =$    | 13632.00         |
| Add 1% L. Cess        | (+)                           |        |                | $P_3 =$    | 1136.00          |
|                       |                               |        |                | $P_3 =$    | 128374.00        |
| Cess below 0.03% (-)  |                               |        |                | $P_3 =$    | 39.00            |
| <u>omprakash</u>      |                               |        |                | $P_3 =$    | 128335.00        |
| J.E.                  |                               |        |                |            | 7.04 25<br>45    |
| Material Statement.   |                               |        |                |            |                  |
| (1) Soil =            |                               | 102.07 | m <sup>3</sup> |            |                  |
| (2) Stone chips =     |                               | 1.19   | m <sup>3</sup> |            |                  |
| (3) Stone metal =     |                               | 4.74   | m <sup>3</sup> |            |                  |
| (4) Emulsion (SS-1) = |                               | 0.37   | m <sup>3</sup> |            |                  |
| <u>omprakash</u>      |                               |        |                |            |                  |
| J.E.                  |                               |        |                |            | 7.04 25<br>45    |

Continuation