

92

[illegible]

23.12.25

Scanned with CamScanner

Sch. XLV- Form No. 134

Particulars	Details of actual measurement				Contents or area
	No.	L.	B.	D.	
2) Re-storation of main culvert					
do do all comp					
Qty. side T.M.S present (97)					
176.8 M ² CR 343.91 / M ²					608292
3) Making up of Burms / Shoulders					
do do all comp					
Qty. side T.M.S present (93)					
126.0 M ² CR 56.29 / M ²					675482
3) Repair of pot-holes					
do do all comp					
Qty. side T.M.S present (94)					
16.92 M ² CR 410.45 / M ²					69452
4) Repair of pot-holes					
do do all comp					
Qty. side T.M.S present (94)					
295.60 M ² CR 250.39 / M ²					564552
5) procuring for patch repair					
do do all comp					
Qty. side T.M.S present (95)					
227.20 M ² CR 265.80 / M ²					610212
6) Main removal of C.D. work					
do do all comp					
Qty. side T.M.S present (91)					
2.00 M ² CR 1109.00 / M ²					221920

(Continuation)

Adjusted
Prisam
23.12.25