

Particulars	Details of actual measurement				Contents of area
	No.	L	B	D	
N/W - Maint. of Road - 120m					
Satya prasad Se Satya gaon					
Agency - Hemant Kumar Singh					
Agg. No - 62/SBD/2019-20					
Date of start - 26/10/2019					
Date of comp - 25/10/2020					
Agg. No of date of comp - 10/12/2020					
Date of measurement - 02/02/2023					
1. Restoration of Raincure					
Beams de - do -					
3x 4.85 x 1.10 x 0.30 =					4.805 m ³
4 x 3.65 x 1.10 x 0.30 =					4.818 m ³
5 x 5.15 x 1.10 x 0.30 =					8.497 m ³
6 x 4.85 x 1.10 x 0.30 =					9.60 m ³
4 x 7.20 x 1.10 x 0.30 =					9.504 m ³
5 x 8.35 x 1.10 x 0.30 =					9.85 m ³
5 x 6.85 x 1.10 x 0.30 =					56.70 m ³

2. Making up of Beams					
Shoulder Surface					
leaved etc do - do -					
2 x 2 x 30 x 0.95 =					114.00 m ²
2 x 4 x 30 x 1.00 =					240.00 m ²
9 x 6.00 x 1.70 =					59.4 m ²
9 x 5.00 x 1.00 =					399.00 m ²
3. Patch repair over					
Bitumen 20 mm mix					
Seal do - do -					
3 x 2.5 x 0.5 =					3.75 m ²
6 x 2.5 x 0.5 =					7.5 m ²
2 x 2 x 3.75 =					15 m ²
					26.25 m ²

Continuation

1x12 12.0000.

~~AD~~
~~SE on 10/2/2022~~

ABSTRACT OF COST

1. Restoration of Barneys

do do
Qty vide TMB P.No - 53
I. No. 56. 70 m^2 @ 410.30 = 23264.20

2. Making up of Beams

Shoulder do do
Qty vide TMB P.No - 53
I. No. 62. 93 @ 25109.20

3. Patch repair Over

Bitumens 20mm
mix seal do do

Continuation

