

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>1st Year Maintenance Bill</u>					
N/WL - Const ⁿ of Road from Kumbha - Rajhar Path to Se					
Sutihar Muslim Tola.					
Ag ^t . No! - 53-S.B.D./20-21					
Agency! - Milon Engin ^g Pvt. Ltd.					
Maintenance Ref ^d ! - 08.08.023 + 007.08.024					
<u>Measurement</u>					
Restoration of Raincut					
$12 \times 4.40 \times 0.80 \times 0.30 = 14.25 \text{ m}^3$					
$16 \times 5.10 \times 0.80 \times 0.30 = 19.58 \text{ m}^3$					
$14 \times 3.10 \times 0.70 \times 0.30 = 9.11 \text{ m}^3$					
$10 \times 3.20 \times 0.80 \times 0.30 = 7.68 \text{ m}^3$					
<u>$= 50.62 \text{ m}^3$</u>					
⑥ Making up Berms/Shoulder -					
$12 \times 4.10 \times 0.90 = 44.28 \text{ m}^2$					
$14 \times 3.80 \times 0.70 = 37.22 \text{ m}^2$					
$10 \times 3.10 \times 1.0 = 31.0 \text{ m}^2$					
<u>$= 112.50 \text{ m}^2$</u>					
③ Maintenance of MSS Road.					
$2 \times 2.34 \times 2.0 = 9.36 \text{ m}^2$					
④ Maintenance of H.P. Culvert					
$= 1.0 \text{ m}^2$					
⑤ Maintenance of Slab Culvert					
$= 1.0 \text{ m}^2$					
⑥ White washed parapet wall					
$= 21.0 \text{ m}^2$					
<u>Sum</u>					
<u>Signature</u>					
20/10/24					
20/10/24					

Continuation

Continuation