

3rd year maintenance

Sch. XLV—Form No. 134

53

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work: Nalanda plateau					
Elevation: Block 544					
So strengthen the ice side					
so ice fall hole huge					
Plastering over fall hole repair					
Amenity: stone mortaring repair					
Actual Date of completion: 4/3/20					

① Restoration of snow cuts - ₹.

$$8 \times 5.00 \times 0.90 \times 0.30 = 10.80$$

$$5 \times 7.50 \times 0.60 \times 0.35 = 5.63,$$

$$\text{Total} = \underline{\underline{16.43}},$$

② Making up broken shoulder etc.

$$8 \times 30.00 \times 0.50 = 120.00$$

$$\text{Total} = \underline{\underline{120.00}},$$

③ Repair of potholes of red brick

75 m² - ₹.

$$8 \times 1.75 \times 1.20 \times 0.075 = 1.264$$

$$\text{Total} = \underline{\underline{1.26}},$$

④ Patch repair over potholes with

20 m² present carpet ₹.

$$8 \times 1.75 \times 1.20 = 16.80$$

$$\text{Total} = \underline{\underline{16.80}},$$

⑤ patch repair over boulders

Surface with 20 m² present carpet ₹.

$$8 \times 2.10 \times 0.90 = 5.67$$

$$10 \times 1.50 \times 0.75 = 11.25,,$$

$$\text{Continuation Total} = \underline{\underline{16.92}},$$

