

(Minister) To 2 to Recg it pur. Das Tole.  
(O.I.Y. below)  
(GEN)

**Schedule XLV-Form No. 134**  
Agency - on LS Baglung Const.

R.D.(W) cliv. Cherkhath DIVISION  
MB No - 1098.

Amanag SUB-DIVISION

Ag no - 175801/19-20

20.8.19

To

19.5.2020

**Measurement Book**



4th Year Maintenance bill

75

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - Construction of Road					
from T.O. 2 to Bagjipur Jhalakata					
Agency - M/s Brijrang Construction					
Agreement No - 1783D/19-20					
Item (1) Restoration of Rain					
CUBS					
10X 5.20 X 1.10 X 0.300 = 17.16 m <sup>3</sup>					
11X 4.50 X 1.15 X 0.300 = 17.07 m <sup>3</sup>					
12X 3.60 X 1.10 X 0.300 = 14.25 m <sup>3</sup>					
4X 1.50 X 0.900 X 0.300 = 1.62 m <sup>3</sup>					
					50.10 m <sup>3</sup>
Item (2) Making up of Banks / Shoulder					
15X 4.00 X 1.10 = 64.00 m <sup>2</sup>					
16X 3.20 X 1.15 = 68.08 m <sup>2</sup>					
12X 3.50 X 1.10 = 46.20 m <sup>2</sup>					
10X 5.50 X 1.15 = 63.25 m <sup>2</sup>					
10X 3.50 X 1.10 = 35.00 m <sup>2</sup>					
					280.18 m <sup>2</sup>
Item (3) Repair of Pot holes					
Filled with 20mm WBM					
2X 0.350 X 0.250 = 0.17 m <sup>2</sup>					
Item (4) Patch repair over					
Pot holes with 20mm					
10X 1.40 X 1.10 = 15.40 m <sup>2</sup>					
14X 1.50 X 1.20 = 25.20 m <sup>2</sup>					
10X 1.60 X 1.10 = 17.60 m <sup>2</sup>					
					58.20 m <sup>2</sup>
Continuation					

Sch. XLV-Form No. 134

# ABSTRACT OF COST

78

## Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(1) 15.1	Restoration of ramule				
	V.T.M.B.P.H. (18)				
	item no (1) — 50.10 M <sup>2</sup>				
	Q 380.58/M <sup>2</sup> — 19067/-				
(2) 15.2(i)	Making up of Party/ shoulder				
	V.T.M.B.P.H. (25)				
	item no (2) — 280.18 M <sup>2</sup>				
	Q 58.32/M <sup>2</sup> — 16354/-				
(3) 15.5	Repair of P.M. holes				
	filled with T.M.B.H.				
	V.T.M.B.P.H. (75)				
	item no (3) — 0.17 M <sup>2</sup>				
	Q 10090.51/M <sup>2</sup> — 15715/-				
	Post holes				
	V.T.M.B.P.H. (25)				
	item no (4) — 58.20 M <sup>2</sup>				
	Q 312.00/M <sup>2</sup> — 13876/-				
(5) 15.3(ii)	Patched repair over Rising of surface				
	V.T.M.B.P.H. (20)				
	item no (5) — 58.43 M <sup>2</sup>				
	Q 206.13/M <sup>2</sup> — 12887/-				
(6) 15.2(i)	Filling of cracks and joints				
	V.T.M.B.P.H. (20)				
	item no (6) — 624 M <sup>2</sup>				
	Q 4.69/M — 2927/-				

Continuation

## Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	V.T.M.B.P.H-(26)				
	160m(12) — 0.72m				
	8 643.25/m — 464m				
(13/18.12.ii)	Cutting of brooches of tree shrubs				
	V.T.M.B.P.H-(27)				
	160m(13) — 5 m				
	8 106.50/m — 533m				
(14/15.12.ii)	Cutting of shrubs fm road way				
	V.T.M.B.P.H-(27)				
	160m(14) — 624 m				
	8 6.54/m — 4081m				
(15/15.12.iii)	Tilling of grass and weeds				
	V.T.M.B.P.H-(27)				
	160m(15) — 1380 m <sup>2</sup>				
	8 2.18/m <sup>2</sup> — 3008m <sup>2</sup>				
(16/15.13)	whitewash of parapet				
	V.T.M.B.P.H-(27)				
	160m(16) — 67.2m				
	8 16.21/m <sup>2</sup> — 1098m <sup>2</sup>				
					96132m <sup>2</sup>
	(less) 0.114(m <sup>2</sup> )				106m <sup>2</sup>
					96026m <sup>2</sup>
Continuation					
A. 1042m <sup>2</sup> 08/10/24 R					