

NAME OF WORK- Dhamari Andhiwari PMUSY Path
SECHAMPUR PMUSY PATH TQ L

Schedule XLV-Form No. 134

~~PMUSY (SC)~~

DIVISION

11111

SUB-DIVISION

Measurement Book

Rajkumar Singh

3rd Year maintenance Bill

37

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work → maintenance of Road from Durwani Adarvi hote to Chakla & Panchayat Path tank Agency → Sri, Raj Kumar Syl App. No. → 44, Panchayat (Sc) / SBD / 2018-19					
Date of S. → 26-2-2019					
Date of A.e. → 11-6-2021					
Date of entry →					
<u>Actual Measurement</u>					
1) Restoration of Road & Shoulder					
29 x 2.5 x 1.1 x 0.300 = 23.925					
17 x 3.0 x 1.0 x 0.3 = 15.30 m ³					
35 x 2.0 x 1.0 x 0.302 = 21.0 m ³					
18 x 2.40 x 1.30 x 0.302 = 16.848 m ³					
20 x 2.2 x 1.20 x 0.302 = 15.84 m ³					
16 x 1.5 x 1.0 x 0.302 = 7.2 m ³					
90 x 1.2 x 1.0 x 0.302 = 7.2 m ³					
22 x 0.75 x 0.5 x 0.302 = 2.475 m ³					
Total 109.80 m ³					
2) making up Beams Shoulder					
— do — do — etc					
28 x 6 x 1.0 = 168 m ²					
17 x 5 x 1.5 = 127.5 m ²					
44 x 0.75 x 0.5 = 16.5 m ²					
Continuation Total 312.0 m ²					

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Absorbed oil cast					
1) Restoration of rain casts					
- do - do - do					
109.80 m ² @ 1/2 side Tr/BP - (37)					
@ Rs 378.32 /m ² Rs 41540=00					
2) making up Beams & Should					
- do - do - do					
312.00 m ² @ 1/2 side Tr/BP - (38)					
@ Rs 5714 /m ² Rs 17828=00					
3) Repair of potholes under					
75 m wBM - do - do					
65 m ² @ 1/2 side Tr/BP - (38)					
@ Rs 404.77 /m ² Rs 26310=00					
4) Patches past over potholes with 2mm premix					
- do - do - do					
65 m ² @ 1/2 side Tr/BP - (38)					
@ Rs 317.79 /m ² Rs 20656=00					
5) Patch repair over damaged surface with 2mm Premix					
- do - do - do					
64.8 m ² @ 1/2 side Tr/BP - (38)					
@ Rs 334.87 /m ² Rs 21700=00					
6) maintenance of C.I.D works (H.P.C) - do -					
	Continuation				

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
7) No° of side Tr/BP - (38)					
1) 110.9.67 / N° 3319200					
8) Maintenance of road signs					
0.23 km of side Tr/BP - (38)					
1) @ Rs 1066.50 / km 245.00					
9) Maintenance of board					
km 200 - do - do					
0.28 km of side Tr/BP - (39)					
1) @ Rs 641.72 / km 180.00					
10) cutting of branched of trees					
2 shrubs - do - do					
11) No° of side Tr/BP - (39)					
1) @ Rs 105.39 / N° 211.00					
11) Trimming of shrubs & trees					
R/w - do - do -					
10 No° of side Tr/BP - (39)					
1) @ Rs 6.47 / N° 65.00					
12) Trimming of grass & weeds					
- do - do - do					
2) 2 of side Tr/BP - (39)					
1) @ Rs 2.16 / m² 52.00					
13) white washing of					
Parapet walls - do - do					
84.0 m² of side Tr/BP - (39)					
1) @ Rs 16.54 / m² Rs 1389.00					

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
137 Poor and laying of hot applied thermoplastic control	—	do	—	do — do	
310 ft of ridge TMBP - (39)					
	@ Rs 924.00/m ²				Rs 286623.00
					Total Rs 420132.00
Less 10% below as per ACP (-)					420132.00
					Net Rs 378115.00
	<i>Mr. S. S. S. 01-11-24 A-E</i>				<i>CP Mr. S. S. S. 01-11-24 E-E</i>

Material Calculated

- 1) E/w $\rightarrow 153 \cdot 72 \text{ m}^3$
- 2) Stone Metal S3 mm 3022.4 $\rightarrow 5.839 \text{ m}^3$
- 3) Stone Screenery $\rightarrow 1.17 \text{ m}^3$
- 4) Bricks (R81) $\rightarrow 0.0325 \text{ m}^3$
- 5) Bricks (S90) $\rightarrow 0.278 \text{ m}^3$
- 6) Crushed Stone chips $\rightarrow 3.89 \text{ m}^3$
- 7) Coarse Sand $\rightarrow 0.779 \text{ m}^3$

Notes
01-11-24
A.G.