

Mangasam Road to Mishir Chak.

Schedule XIV-Form No. 134

E-E R.W.D. (W)

DIVISION

H.E. K. (W)

SUB-DIVISION

WAZIR KHAN

MEASUREMENT BOOK

M. Adoni Construction.

3060

प्रमाणित किया जाता है कि इस मापी हुई
अंख्या 3060 से अधिक द्वारा भूमि का

1.

Name of work -

Situation of work -

Agency by which work is executed -

Date of measurement -

No. and date of agreement.

(These four lines should be repeated at the commencement of the measurements relating to each work).

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Iron AC Ball					
Name of work: Const of rural road					
from Mangrawan Road					
To Misirchak Under					
M Masry (SC)					
Gen of: M/s Aadish Const					
Agth no: 124/530/111 Masry/SC/2021					
SOW: 8.3.2021					
TOC: 7.3.2022					
Date of measurement: 16.5.22					
(Const of reference)					
Bench Mark Pillar					
2.214 Km					
(a) Clearing & grubbing					
of road bed & side					
20 x 30.00 x 7.00 = 4200.00					
20 x 30.00 x 7.00 = 4200.00					
20 x 30.00 x 7.00 = 4200.00					
13 x 30.00 x 7.00 = 2730.00					
1 x 10.00 x 6.50 = 65.00					
15395.00					
or 1.53 Hect					
C/O					

Continuation

1st Year Maintenance Bill

48

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work- Const of rural road from Mangarwan road to Hissickah Under MMHSY (SC)					
Agency- M/s Aadarch Const.					
Aggt No- 124/SBD/ MMHSY/SC/20-21					
Dow - 8.03.21					
ToC - 7.03.22					
Date of final Measurement - 24/12/23					
(1)	Restoration of main cut.				
				112.0543	
(2)	Making up of Beams/ Shoulder, stripping excess soil.				
				622.6942	
(3)	Repair of Pot holes				
				0.1643	
(4)	Patch repair over Pot holes.				
				51.8942	
(5)	Patch repair over Bituminous.				
				51.89	
(6)	Crack sealing filling of cracks and joints.				
				2214.004	

Continuation

Particulars	Details of actual work done			Contents of area
	No.	Q.B.	D.	
		7-11-2008		
		Abstract of cut		
(1)	Restoration of section cuts			
P/48		112.0843		
	Q	404=06		B= 45287=00
(2)	Making up of Roadway shoulder.			
P/48		622.6942		
	Q	60=28		B= 37536=00
(3)	Repair of Pot holes			
P/48		0.1643		
	Q	8933=60		B= 1429=00
(4)	Patch repair over Pot holes			
P/48		51.8942		
	Q	234=75		B= 12181=00
(5)	Patch repair over bituminous.			
P/48		51.8942		
	Q	250=88		B= 13018=00
(6)	Filling of cracks over Joint.			
P/48		2214.004		
	Q	3=71		B= 8214=00

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(14)	Kite marking of parapet.				
P/49		147.00 M ²			
	①	16.80			16 = 2470 = 00
					16 = 163478 = 00
Add 2% loss (+)					16 = 19617 = 00
Add 1% loss (+)					16 = 1635 = 00
					16 = 184730 = 00
1/1000					
27/12/24					
JE					

Material statement

- (2) E/W - 112.08 M³
 (22) S/C lips - 1.40 M³
 (222) Bitumen - 0.098 M³ T

~~1/1000~~
~~27/12/24~~
~~JE~~