

# 4th year maintenance Bill

81

Sch. XLV—Form No. 134

| Particulars | Details of actual measurement |    |    |    | Contents of area |
|-------------|-------------------------------|----|----|----|------------------|
|             | No.                           | L. | B. | D. |                  |

Name of work— maintenance of road from  
Reo road Shyamana Pandit house to kangle

Totbanch

Agency— Ramesh Kumar

Agreement No— 14-M.B.D-2019-2020

Date of start— 09-08-2019

Date of completion— 08-08-2020

Actual date of completion— 05/11/2020

(Re-work measurement)

1) Restoration of raincuts - - - - of ell

$$07 \times 05 \left( \frac{0.90 + 0.80}{2} \right) \times 0.300 = 8.92 \text{ m}^3$$

$$10 \times 08 \left( \frac{1.10 + 1.0}{2} \right) \times 0.300 = 25.2 \text{ m}^3$$

$$09 \times 05 \left( \frac{1.20 + 1.0}{2} \right) \times 0.300 = 21.7 \text{ m}^3$$

$$05 \times 05 \left( \frac{1.00 + 1.10}{2} \right) \times 0.300 = 9.45 \text{ m}^3$$



Scanned with OKEN Scanner



| Particulars                         | Details of actual measurement |               |    |    | Contents of area      |
|-------------------------------------|-------------------------------|---------------|----|----|-----------------------|
|                                     | No.                           | L.            | B. | D. |                       |
|                                     | 12 X 11                       | (0.90 + 0.80) |    | =  | 112.2 m <sup>2</sup>  |
|                                     | 12 X 10                       | (1.10 + 1.0)  |    | =  | 126 m <sup>2</sup>    |
|                                     |                               |               |    |    | 834.05 m <sup>2</sup> |
| 3) Repair of pot holes ----- of c/c |                               |               |    |    |                       |
|                                     | 02 X 1.80 X 2.10 X 0.075      |               |    | =  | 0.56 m <sup>3</sup>   |
|                                     | 02 X 1.90 X 1.80 X 0.075      |               |    | =  | 0.51 m <sup>3</sup>   |
|                                     | 02 X 3.20 X 2.10 X 0.075      |               |    | =  | 1.39 m <sup>3</sup>   |
|                                     | 02 X 2.10 X 2.80 X 0.075      |               |    | =  | 1.21 m <sup>3</sup>   |
|                                     | 02 X 1.20 X 2.20 X 0.075      |               |    | =  | 0.39 m <sup>3</sup>   |
|                                     | 02 X 1.30 X 1.50 X 0.075      |               |    | =  | 0.29 m <sup>3</sup>   |
|                                     | 02 X 3.30 X 3.40 X 0.075      |               |    | =  | 1.68 m <sup>3</sup>   |
|                                     | 02 X 3.40 X 3.50 X 0.075      |               |    | =  | 1.78 m <sup>3</sup>   |
|                                     | 02 X 3.35 X 3.50 X 0.075      |               |    | =  | 1.75 m <sup>3</sup>   |
|                                     |                               |               |    |    | 9.56 m <sup>3</sup>   |

|                                             |                  |  |  |   |                       |
|---------------------------------------------|------------------|--|--|---|-----------------------|
| 4) Patch repair over pot holes ----- of c/c |                  |  |  |   |                       |
|                                             | 02 X 3.20 X 2.10 |  |  | = | 18.56 m <sup>2</sup>  |
|                                             | 02 X 2.80 X 2.10 |  |  | = | 15.12 m <sup>2</sup>  |
|                                             | 02 X 1.90 X 2.10 |  |  | = | 7.98 m <sup>2</sup>   |
|                                             | 02 X 2.20 X 3.10 |  |  | = | 13.64 m <sup>2</sup>  |
|                                             | 02 X 2.50 X 2.60 |  |  | = | 13 m <sup>2</sup>     |
|                                             | 02 X 2.40 X 2.50 |  |  | = | 12 m <sup>2</sup>     |
|                                             | 02 X 3.60 X 3.50 |  |  | = | 25.2 m <sup>2</sup>   |
|                                             | 02 X 3.30 X 3.40 |  |  | = | 21.76 m <sup>2</sup>  |
|                                             |                  |  |  |   | 127.26 m <sup>2</sup> |

|                                              |                 |  |  |   |          |
|----------------------------------------------|-----------------|--|--|---|----------|
| 5) maintenance of clb work H.P. ----- of c/c |                 |  |  |   |          |
|                                              | 1.00 X 0.2 N.O. |  |  | = | 0.2 N.O. |
| 6) maintenance of clb work S.C. ----- of c/c |                 |  |  |   |          |
|                                              | 1.00 X 0.2 N.O. |  |  | = | 0.2 N.O. |

(abstract of cost)

1) Restoration of masonry  
of e/i qty vide tmb P- (81)

$$141.73 \text{ m}^3 @ 380.58/\text{m}^3 = 53940/2$$

2) making up of beams  
of e/i qty vide tmb P- (81)

$$834.05 \text{ m}^2 @ 58.37/\text{m}^2 = 48859/2$$

3) Repair of rat holes  
of e/i qty vide tmb P- (82)

$$9.56 \text{ m}^3 @ 11215.53/\text{m}^3 = 107220/2$$

4) Patch repair over rat holes  
of e/i qty vide tmb P- (82)

$$127.26 \text{ m}^2 @ 290.66/\text{m}^2 = 36989/2$$

5) maintenance of dp work HPC  
of e/i qty vide tmb P- (82)

Continuation

$$02 \text{ Nos} @ 1117.00/\text{Nos} = 2234/2$$