

बिहार सरकार
कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, लखीसराय

पत्रांक:- 279

लखीसराय/ दिनांक:- 18-02-2025

प्रेषक,

ई० आशुतोष कुमार
कार्यपालक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमंडल लखीसराय।

सेवा में,

नोडल पदाधिकारी
नई अनुरक्षण नीति 2018 (MR 3054),
ग्रामीण कार्य विभाग, बिहार, पटना।

विषय:- MR 3054/ नई अनुरक्षण नीति 2018 के अन्तर्गत Ophapur More - Harijan Tola पथ में कराये गये कार्य के विरुद्ध में आवंटन उपलब्ध कराने के संबंध में।

महाशय,

उपर्युक्त विषय के संबंध में सूचित करना है कि MR 3054/ "नई अनुरक्षण नीति 2018" के अन्तर्गत Ophapur More - Harijan Tola पथ कार्य पूर्ण हो चुका है। उक्त पथ में किये कार्य का भुगतान हेतु कुल 29.52609 लाख (उनतीस लाख बावन हजार छः सौ नौ) मात्र के भुगतान हेतु आवंटन की अधियाचना विहित प्रपत्र में तैयार कर समर्पित की जाती है।

अतः सादर अनुरोध है कि शीघ्र आवंटन उपलब्ध कराने की कृपा की जाय।
अनु०-यथोक्त।

विश्वासभाजन


(ई० आशुतोष कुमार)
कार्यपालक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमंडल लखीसराय

RWD Works Division, Lakhisarai

Requisition Format for Scheme Head- MR (3054) Under Bihar Rural Road " New Maintenance Policy 2018" (Initial Rectification and Surface Renewal)

Name of Division:- Lakhisarai

S. N	Package No.	Name of Road	Project ID as per MIS	Administrative Approval (A.A) Letter No. & Date	Administrative Approval (A.A)		Agreement Amount (in Lakh)		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI in MM/KM	Thickness of Bitumen Layer (in MM)	Value of Bitumen Content (in %)	Previous Total Allocated Amount (in Lakh)	Up-to-date expenditure as per MIS (in Lakh)	Requisition against work done (in Lakh)	Remarks
					Length (K.M)	Amount (in Lakh)	Initial Rectification with Surface Renewal (in Lakh)	5 Year Routine Maintenance										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
	MR-N/23-24 Lakhisarai/ 25	Ophapur More- Harijan Tola	RM/LA/LAK/ 24/0002	6120 & 04.12.2023	1.800	106.33000	62.15087	14.69040	01/MBD/24-25 & 17.06.2024	16.03.2025		3134.42	PCC	-	0	0	29.52609	PCC

15/02/2025
TS

18/01/25
AB

Executive Engineer
RWD Works Division Lakhisarai

18/01/25

Ophapur More To Harijan Tola`

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI\TEGORY mm/km ROAD	Latitude	Longitude	Event
15/2/25	11:13:54	131	0.1	270	0	2700	3199 G	25.144386	86.066118	Normal
15/2/25	11:14:39	131	0.1	260	10.1	2600	3086 G	25.143134	86.065929	Normal
15/2/25	11:14:59	131	0.1	280	20.2	2800	3313 G	25.14206	86.065724	Curve
15/2/25	11:15:24	131	0.1	260	20.2	2600	3086 G	25.141505	86.065628	Normal
15/2/25	11:15:48	131	0.1	250	20.2	2500	2972 G	25.140419	86.065531	Normal
15/2/25	11:16:16	131	0.1	280	20.2	2800	3313 G	25.140338	86.064502	Curve
15/2/25	11:16:41	131	0.1	250	20.2	2500	2972 G	25.140378	86.063178	Normal

3134.42

$$Y = 0 * X^2 + 1.136 * X + 132.5$$

$$X = 2500$$

$$Y = 2972$$

(R) RURAL ROAD

Good Average Poor
<4000 4001-5000 >5001

15/02/2028
rs

15/02/25
H.R.

15/02/25

Name of Customer : Manoj Kumar Singh
Name of Work/ Road : Ophapur More To Harijan Tola
Lab Job number : 131
Date : 15-Feb-25
Section No. : 131

Test Date : 15-Feb-25
Machine No. : 484
Road Name : Ophapur More To Harijan Tola
Road Type : (R) RURAL ROAD
Start S No. :
Start E No. :
Side :
Interval :
Weather :
U/V Range : 1972 To 4000 mm/km
Dist Range : 0 To 0.8 0.1 1000 m
Start Location :
End Location :
Equation : test


Print

Generate Report and Graph

Redraw Graph

Map View

File : C:\Users\user\Desktop\Ophapur More To Harijan Tola.Xls, Section No.: 131, Eqn: test
 Name of Customer : , Name of Work/ Road : , Lab Job number :



Handwritten signature

Handwritten signature and date 15/2/25

Handwritten signature