

57

[illegible]

Measurement

① Restoration of Reim Cut T15			
8x	5x	0.90x0.6	= 21.6
10x	5.2x	0.9x0.6	= 28.08
12x	4.5x	0.9x0.6	= 29.16
12x	4.1x	0.9x0.6	= 35.42
18x	3.5x	0.9x0.6	= 34.02
12x	3x	0.9x0.6	= 19.44
12x	3.2x	0.9x0.6	= 20.73
15x	2.5x	0.9x0.6	= 20.25
14x	2x	0.9x0.6	= 15.12
15x	1.8x	0.9x0.6	= 14.58
21x	2.1x	0.9x0.45	= 17.86
16x	2.4x	0.9x0.45	= 15.55
5x	2x	1.0x0.6	= 6

Continuation

Continuation

Total

277.81 age

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
⑥ Mainf. of 200 M Stone 715					
2.8 km wide TMB P. 93					
⑦ E 683.74 / M					1914
⑦ Mainf. of Road 715					
2.8 km wide TMB P. 93					
⑧ E 1020.55 / KM					2852
③ Total					310448
Add 10% below					31045
④ Total					279403
⑤					

Bhart Petroleum

Invoice No - 4520406215

dt - 22/7/24

Qty = 2.716 MT

K
31/8/24

materials Statement

E/W = 510.73 m³Stone 27 m³

Bitumen = 481 Kg

K
31/8/24