

LO36 (JARSO DOKARAM PATH) TO
PASWAN TOLA

Schedule XLV-Form No. 134

BENIPUR

MMHSY-SC
DIVISION

BENIPUR SUB-DIVISION

MEASUREMENT BOOK

M.B.No-1328

श्री केशी कुमर

SB/2019-20

300 year maintenance

Sch. XLV-Form No. 134				Contents of area
Particulars	Details of actual measurement			
	No.	L.	B.	
Name of work: -				
path to prison + to				
temple SV (SC)				
Agreement No. -				
Name of Agency -				
Date of start -				
Date of comp -				
Actual date / comp				
to Restoration / Ram cut				
1 x 8.6 x 0.80 x 0.20 =				1.37
1 x 1.5 x 0.5 x 0.20 =				0.15
2 x 3.4 x 1.8 x 1.10 =				13.46
1 x 4.6 x 1.2 x 0.50 =				4.97
1 x 2.6 x 0.4 x 0.20 =				0.20
1 x 4.2 x 0.6 x 0.30 =				0.75
2 x 5.2 x 2.10 x 0.50 =				12.65
3 x 4.6 x 1.90 x 0.80 =				20.97
1 x 2.2 x 0.60 x 0.50 =				0.66
1 x 1.6 x 0.40 x 0.30 =				0.19
1 x 2.2 x 0.8 x 0.30 =				0.52
2 x 4.8 x 2.4 x 0.70 =				16.12
1 x 5.10 x 1.90 x 1.10 =				10.66

Continuation 85.67m

Abstract/cont
3rd year marks

46

Sch. XLV-Form No. 134

Particulars	Details of actual measurement			Contents of area
	No.	L.	B.	
1) Restoration / Repairing 109.52m ² C.V. 7m ² RN-42				
Qd 386.14/m ²				42230=
2) Making up / Booming / Shoulders Supply excess soil from the shoulder				
610.57m ² C.V. 7m ² RN-43				
Qd 5736m ²				→ 35092=
3) Repair / pot / Culvert with 7.5m x 1.25				
7.5/9.3 C.V. 7m ² RN-44				
Qd 10957.07/m ²				→ 82328=
4) Part / Depart over pot with 11.13.2 C.V. 7m ² RN-45				
100.48m ² C.V. 7m ² RN-45				
5 @ 1270/m ²				→ 127129=
5) Maintenance / C.V. work (11.13.2)				
4m C.V. 7m ² RN-45				
Qd 1130.6/m ²				4522 4523=
6) Maintenance / Repair with 12.2				

Continuation

→ 191292=

BRK 191282

