

Samhuta PMSY Path to Mohriya
Anusuchit Jati toli

Schedule XLV-Form No. 134

Hect - MMSY (SC)

Buxar

Rajpur

SUB-DIVISION

DIVISION

Measurement Book

No. 1321

1/1/2023

70
Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
4th year Maintan-					
Name of work - Samakul&PMG by					
To Moharsiya Amuselut Jati					
Tola.					
Agency - Balleshwar Singh					
Ag No - 10810D / 18-19					

① Restoration of gullies

$$6 \times 30 \text{ m} \times 1.125 \times 0.95 = 50.625 \text{ m}^3$$

$$10 \times 30 \text{ m} \times 1.05 \times 0.25 = 78.75 \text{ m}^3$$

$$4 \times 25.5 \times 0.1 \times 0.25 = 25.05 \text{ m}^3$$

$$\text{Total} = 157.39 \text{ m}^3$$

② Maintenance of shoulders

$$10 \times 30 \text{ m} \times 1.125 = 337.5 \text{ m}^2$$

$$10 \times 30 \text{ m} \times 1.10 = 330.0 \text{ m}^2$$

$$5 \times 8.0 \times 1.05 = 42.0 \text{ m}^2$$

$$1047.05 \text{ m}^2$$

③ Repair of potholes by mixing

$$5 \times 3.90 \times 1.65 \times 0.05 = 32.175 \text{ m}^3$$

$$4 \times 6.50 \text{ m} \times 2.10 \times 0.05 = 52.92 \text{ m}^3$$

$$5 \times 6.90 \text{ m} \times 2.25 \times 0.05 = 58.25 \text{ m}^3$$

$$4 \times 3.45 \text{ m} \times 1.90 = 23.94 \text{ m}^2$$

$$186.63 \text{ m}^2$$

④ Repaired by mixing & surfacing 100 cm

$$= 186.63 \text{ m}^2$$

Continuation

(4) Manufacture of soft Soles by M.C.S.
Sch. XLV-Form No. 134 Dated 209-22/1939/47/10

Continuation