

MSABARD.

Schedule XLV-Form No. 134

Cont. of HL RCC Bridge in Place of
Damaged Screw pile Bridge at
Ratanpatti Road **KODALI DIVISION**

Madhepura - Division.

Kumarkhand-**SUB-DIVISION**

MB No. - 1909

MEASUREMENT BOOK

Arbind Kumar

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
				P.F - W 3,16,94,416 →	
(11/24) S.P.R. P.O.T - T.T.A.E					
beaming —					
G.W. L.V. T.H.B. (1-25)					
@ R 51114.04 / each					3,06,684 →
(12/28) P.V. unimp. holes					
—					
130. W.L. L.V. T.H.B. (1-25)					
@ R 157.48 / each					20,472 →
					↓
				F.W 3,20,21,572 →	
Add O.S. @ 18% —					(1) 57,63,883 →
Add L.P. 1% —					(1) 3,20,216 →
Add S.F.C. —					R 1,11,332 →
Add S.F.C. (for thin bill) —					22,797 →
					↓
T.W. 3,82,41,797 →					
Less O.D.T. below —					M 26,769 →
					T.W. 3,82,15,028 →
Less previous payment —					B 3,29,62,677 →
					↓
					N.C. 52,52,357 →
21/01/25					
21/01/25					
21/01/25					

Continuation