

1st Yearly Maintenance

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Named Chausa lowligam PMUay					
Road to near Laxman					
Mosjidul					
BA - Raknash kr Raknag					
Agg M -					
Recorded entries					
① Restoration of Rain cut					
	2x	10x	0.9x	0.30	= 5.40
	2x	30x	0.6x	0.9	= 18.00
	5x	30x	0.60x	0.30	= 27.00
	2x	30x	0.6x	0.50	= 18.00

					72 = 68.40
					Unit 72 = 68.34 cum cum
② Working of Shoulder					
	5x	30x	0.90		= 21.00
	6x	30x	0.90		= 162.00
	10x	30x	0.75		= 225.00
					= 471.00
					sqm
⑤ Patch repair on already filled					
	2x	10x	0.60		= 12.00
	4x	5x	0.90		= 18.00
	10x	0.6x	0.30		= 1.80
					= 31.80
					sqm

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(5) Patch repair on pot hole					
vide Item No 5 P/17					
31.64 sqm @ 235.50					
					= 7451.00
(7) Mains of G/D					
vide Item No 7 P/20					
1.0 Nos @ 1182.79					
					= 1183.00
(9) Mains of Road Sign					
vide Item No 9 P/20					
2.17 km @ 1117.64					
					= 187.00

(10) Mains of Box man					
vide Item No 10 P/20					
0.20 km @ 588.84					
					= 118.00
(11) cutting of breach of d/c					
vide Item No (11) P/20					
3.0 Nos @ 115.57					= 347.00
(12) cutting of sharps					
14.0 Nos @ 7.10					= 99.00
					7265788.00
					= 7895.00
Add 22% GST					= 658.00
Add Adv. L					= 750.00
Add 15% P					75091.00
Below 0.0 L/v					= 7.00
					75087.00

Approved
05/01/2024
JE

Continuation
05/01/2024
AE

C&V
7.1.24