

messy (Gen)

MB No - 716-2

24-25

Schedule XLV-Form No. 134

PWD-Sachak. G.N. Boudh to yadav Tola-ferder

श्रीशं. शर्मा

DIVISION

अपेक्षित शर्मा

SUB-DIVISION

MB No - 716

57

Measurement Book

Bickhan Chandra Kumar

प्रमाणित किया जाता है कि इस
मापी पुस्तक में मशीन द्वारा अंकित
कुल - 100 (रुक सौ) पन्ने हैं जो
सम्बन्धित अभियंता, मापीय कार्य
विभाग कार्य अवर प्रमोशन, गोगरी
को निर्गत किया जाता है।

Sany 29/10/24
Executive Engineer
R.W.D. Works Div.

Bask 29/10/24
Sany

Sch. XLV - Form No. 134

प्रमोशन. गोगरी DIVISION
अवर प्रमोशन. गोगरी SUB-DIVISION

Measurement Book

716

No.

Name of officer _____

4th year maintenance

1

Name of Work—
 Situation of Work—
 Agency by which work is executed—
 Date of Measurement—
 No. and date of agreement

(These four lines should be repeated at the commencement of the measurement relating to each work)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work: - maintenance of road from Jamalpur Boriya bathan road Revd Sadak G.M Bandh to yadav tola under munsy men					
Name of Agency: - Bidharach Andra kumari					
Date of Commencement: - 28-11-2019					
Date of Actual completion: - 01-10-2020					
Date of entry: -					
(i) Restoration of samcuts / Berms shoulder stripping of excess soil - - cu					
Cont. job					
$1 \times 10 \times 3m \times 1.50m \times 0.30m =$					$13.50m^3$
$1 \times 10 \times 8m \times 1.20m \times 0.30m$					$= 18m^3$
$1 \times 10 \times 8m \times 0.95m \times 0.30m$					

Continuation: - 22.80m³

Abstract of Cost

5

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(1) Restoration of rammed berms with soil moored etc. - all work job					
at vide in this m.B.					
P. no (2) item no (1) =					
104.864 m ³					
@ 379.50/m ³ ———					39729 =
(2) Making up of berms/ Shoulder stripping of exc. on road - all work job.					
at vide in this m.B.					
P. no (2) item no (2)					
442 m ² @ 56.81/m ² ———					26814 =
(3) Repair of pot holes filled with as m — all work job					
at vide in this m.B. P. no					
(3) item no (3) = 102.69 m ²					
@ 308.32/m ² ———					31661 =
(4) Patch repair over old hole with bitumen premix carpet - all work job					
at vide in this m.B. P. no					
(3) item no (4) = 102.69 m ² @ 166.66/m ²					17114 =

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(5) Patch repair mes bitu minious Surface - - and comp. job					
at vide in this m. B. P. no					
(3) item no. (4) = 102.69 m ²					
@ 184.47/m ² - - - - -				15	18943 =
(6) maintenance of slab culvert					
at vide in this m. B. P. no					
(4) item no. (6) = 290					
@ 2273.47/each - - - - -				4	4547 =
(7) maintenance of road ston					
at vide in this m. B. P. no					
(4) item no. (7) = 0.20 km					
@ 1054.28/km - - - - -				2	11 =
(8) maintenance of 200m and km Stone					
at vide in this m. B. P. no					
(2) item no. (8) = 0.23 km					
@ 613.36/km - - - - -				2	141 =
(9) Acclivity at branch at trees and shrubs					
at vide in this m. B. P. no					
(4) item no. (9) = 370					
@ 106.12/each - - - - -				4	318 =

Continuation

[illegible]