

Puliyur Path to Belirampur Path Tuk  
MMSY (G.E.Y)

# Schedule XLV-Form No. 134

Buxkar DIVISION

BUXKAR SUB-DIVISION

## Measurement Book

1420

Krig - Sanjai Brothers comd. M.V.C.T.D.

## 4th Year Maintenance

54  
Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/W - Putra Path to Bali rampur					
Under MM nsy (new)					
Agen CVT Sanjeev Brothers Constructions Ltd.					
Agg-NW-49 SBD of 2019-20					
Date of Survey 7-12-2019					
Actual date of Comp - 21-03-2020					
Date of Survey					
Item of work					
1) Preparation of Excavations / Basins with Soil Mixing - etc					
$2 \times 4 \times 30 \times 1.0 = 1.2m \times 0.8m = 72.00 m^3$					
2) Making up of Basin / Shallow					
stripping - cleared soil -					
$2 \times 2 \times 30 \times 1.125 = 135.00 m^3$					
$2 \times 2 \times 30 \times 1.10 = 120.00 m^3$					
$2 \times 2 \times 30 \times 0.63 = 75.60 m^3$					
Total Qty = $404 = 404.60 m^3$					
3) Repair of path holes filled					
Cubic 75 mm WBM 2x1.5					
$4 \times 5-w \times 1.50 \times 0.075 = 2.40 m^3$					
$3 \times 7-w \times 1.50 \times 0.075 = 2.362 m^3$					
$3 \times 6-w \times 1.50 \times 0.075 = 1.62 m^3$					
Total Qty = $6.382 m^3$					

Continuation

Sch. XLV-Form No. 134

## **Continuation**

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/W -	5th B tit at your masterpiece at road from Pulupetty to Balarampur under Muzey (new)				
Agent/ Sengar Brothers Const. Pvt. Ltd					
Age ADP-49 EBD at 2019-2020					
Date of start 7-12-2019					
Date of completion					
Actual date of completion 20-12-20					
Date of survey					
Item of work:					
① Preparation of concrete floor with sand 50 mm x 20 -					
2 x 3 x 30 x 1.20 x 0.30 = 60.72 m <sup>3</sup>					
2 x 1 x 30 x 1.120 x 0.30 = 20.25					
Total Qty 81.00 m <sup>3</sup>					
② Making up of brick/stone					
Brick ence 100x45x20 -					
2 x 4 x 30.00 x 1.10 = 264.00 m <sup>3</sup>					
2 x 3 x 30.00 x 1.05 = 189.00 m <sup>3</sup>					
Total Qty 453.00 m <sup>3</sup>					
③ Repair of brick wall					
With 75 mm WBM x 1.50 --					
5 x 2.10 x 1.50 x 0.075 = 3.181 m <sup>3</sup>					
2 x 2.1 x 7.75 x 0.075 = 1.687 m <sup>3</sup>					
4 x 9.00 x 1.30 x 0.075 = 3.51 m <sup>3</sup>					
2 x 7.20 x 1.50 x 0.075 = 1.597 m <sup>3</sup>					

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
B.12					P3- 113315 m <sup>2</sup>
8/9) Maintenance of 200 m <sup>2</sup>					
1 KM Stone do - all comp					
QH 4 + 0.22 m wide road					
@ 46.715 / km					P3- 162 m <sup>2</sup>
9/10) (b) Cutting of branches of tree					
8 shrubs - do -					
QH 4 2 nos wide road					
Path 52 m wide					
@ 93-20 / each					P3- 187
(10) Cutting of shrubs from road way					
After do nos path 59					
@ 6.20 / each					P3- 62
total cutting area for shrubs					
width of 200 m road					
QH 4 L 52 m wide path 59					
@ 15.44 / m <sup>2</sup>					P3- 803 m <sup>2</sup>
					P3- 114469 m <sup>2</sup>
Add @ 12.7. 687					12 13736 m <sup>2</sup>
Add @ 1. 8 rebs					12 1145 m <sup>2</sup>
					12 129350 m <sup>2</sup>
Less 10 m below ↘					12 12975 m <sup>2</sup>
					12 116615 m <sup>2</sup>

## **Continuation**