

1 Styer Mantau Hill

30°

Sch. XLV—Form No. 134

Sch. XLV—Form No. 134					Contents of area
Particulars	Details of actual measurement				
	No.	L	B	D	
Name of work	Tola to Chhata Harisan				
	Tola Naxali				
Agency	Bri Mahesh Kumar Singh				
Agent's	57 SABD) 20-21				
	<u>work done</u>				
① Restoration of main cut - do - do -					
	10 x 1.	1.125	2.5	3 m	3.375 m ³
	15 x 1.	1.125	3	3 m	5.062 m ³
	20 x 5.0	1.125	3	3 m	33.75 m ³
	6 x 10 x	1.125	3	3 m	20.25 m ³
	4 x 1.0 x	1.125	3	3 m	1.35 m ³
					<u>63.787 m³</u>
					63.28 m ³
② Make up berm - do - do -					
	6 x 10.00	1.50			90.00 m ²
	10 x 12.0	1.50			180.00 m ²
	3 x 10.0	1.0			30.00 m ²
	5 x 10.0	1.0			50.00 m ²
	1.50	1.0			<u>1.56 m²</u>
					351.56 m ²
③ Pot repair overburden - do - do -					
	4 x 5.0	1.0			20.00 m ²
	1 x 2.27				<u>2.27 m²</u>
					22.27 m ²
④ Maintenance of D - do - do -					
	1 x 1.30	0.7			1.01 m ²
⑤ Maintenance of road - do - do -					
	1 x 0.13				0.13 km
⑥ Maintenance of 200m stone					

Continuation

1 x 0.13 = 0.13 km

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
⑦ Cully of branches - do -					
vide mms P - ③①					
ab = 3.40 Nm					
CR 109 = 74 / Nm					R 329 = 00
⑧ Cully of shanks - do -					
vide mms P - ③①					
ab = 13.40 Nm					
CR 6 = 73 / Nm					R 87 = 40
⑨ Timber of stairs - do -					
vide mms P - ③① ab = 5.76 m ²					
CR 2 = 24 / m ²					R 13 = 00
⑩ Wholes of shanks - do -					
vide mms P - ③① ab = 21.40 m ²					
CR 17 = 59 / m ²					R 369 = 00
					<u>52700 =</u>

Add 12% G.S.T (H) R 6324 = 40

Add 1% L.C (H) R 527 = 40

R 59551 = 40

Less 10% below (H) R 5955 = 00

R 53596 = 00

Done
15/6/2024