

Name of work - Rahi Itala to Kopa Itala road

Gr. 7.5. N.Y

Measurement Book

Schedule XLV-Form No. 134

PT0073740

Biraul

DIVISION

Biraul

MB No - 1032

SUB-DIVISION

AGENCY - SRI Jini dar Yadav

Abstract of cost

① Restoration of rainculs

P/35 94.38 m³

Limited to 67.50 m³

@ 378.32/m³ = 25536/-

② Maintenance of shoulder

P/36 388.2 m²

Limited to 365.63 m²

@ 57.35/m² = 20969/-

③ Maintenance of CD work

P/36 03 Nos

@ 1109.67/Nos = 3329/-

Continuation

Continuation