

mmby-sc Ledger ID-409

Satahan Sharma to Satahela
Schedule XLV-Form No. 134

DIVISION

Pibra.

SUB-DIVISION

M.B. No- 807

MEASUREMENT BOOK

M/s Balasi Traders

Sch. XLV-Form No. 134					
Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Restoration of Raincut					
Berms — do —					
4	17	1.25	0.30	=	25.50 m ²
3	11	1.10	0.30	=	10.89 "
2	9	1.00	0.30	=	5.40 "
7	12	0.90	0.30	=	22.68 "
				=	64.47 m ²
				Limit :	56.30 m ²
② Making up of Berms					
of shoulder — do —					
4	15	1.10		=	66.00 m ²
5	21	1.25		=	131.25 "
7	9	0.90		=	56.70 "
3	25	1.00		=	75.00 "
7	9.0	1.10		=	69.30 "
				=	398.25 "
③ Maintenance of potholes					
75 BM — do —					
5	15	1.80	0.075	=	10.12 m ²
8	21	2.00	0.075	=	25.20 "
6	25	2.15	0.075	=	24.19 "
5	15	1.00	0.075	=	5.60 "
				=	65.12 m ²

Continuation

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Abstract					
① Restoration of Raincut/					
Burns -do-					
56.30 m ³ Vole MB P-60					
② Rs 404.06/m ³ = Rs 22749.00					
② Making up of Burns of					
Shoulders -do-					
398.25 m ² Vole MB P-60					
③ Rs 60.28/m ² = Rs 24007.00					
③ Repair of Potholes					
filled with 75 mm.					
65.12 m ³ Vole MB P-60					
④ Rs 322.96/m ³ = Rs 21031.00					
④ Patch repair on already					
filled WBM -do-					
65.12 m ² Vole MB P-61					
⑤ Rs 251.08/m ² = Rs 16350.00					
⑤ Maintenance of H.P Cement.					
IND Vole MB P-61					
⑥ Rs 1166.58/IND = Rs 1167.00					

Continuation = Rs 85304.00

