

111165X NEW (Gen) M.B.No. 3470

Schedule XLY-Form No. 134

સેકશનલ જાહેરાત બેંક ઓફ ગુજરાત પ્રાઇવેટ લિમિટેડ દ્વારા
પર ૧૯/૦૫/૨૦૨૧ ના રોજ
પ્રકાશિત થયેલ - ૩૧/૦૫/૨૦૨૧ ના રોજ
સુધા. જી. સુધા સુધા (સુધા સુધા)
જી. સુધા સુધા (સુધા સુધા)

જાહેરાત

SUB-DIVISION

Fig Amt. 34 65 340

MEASUREMENT BOOK

M.B.No - 3470

3rd Year Maintenance Bill :-

Record Entry:-
Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>Nil:- Construction of road from</u> <u>Teknusa Talapur Road to Pathmik</u> <u>vidyalay Balua To Chaka Bazar Tah</u> <u>Name of Agency:- Karakna Interpriser</u> <u>Agg. No:- 39/SBD/2021-22</u> <u>Date of started:- 15/01/22</u> <u>Date of completion:- 14/05/22</u>					
<u>1) (15.1) Restoration of Raincure,</u> <u>beams with soil masonry</u>					
2 No. x 2 mtr x 0.70 x 0.30					3.36 m ³
2 No. x 5 mtr x 0.70 x 0.30					2.10 m ³
6 No. x 4 mtr x 0.70 x 0.30					5.04 "
7 No. x 2 mtr x 0.70 x 0.30					4.41 "
4 No. x 6 mtr x 0.75 x 0.30					5.04 "
2 No. x 5 mtr x 0.75 x 0.30					3.375 "
6 No. x 4 mtr x 0.75 x 0.30					5.40 "
5 No. x 8 mtr x 0.75 x 0.30					3.375 "
10 No. x 3.5 mtr x 0.75 x 0.30					7.875 "
9 No. x $\frac{3}{2}$ mtr x 0.75 x 0.30					6.075 "
					<u>46.05 m³</u>
<u>(15.2) Making up of Beam,</u> <u>shoulder, stripping excess</u> <u>soil from the shoulder surface</u> <u>— lane etc</u>					
2 side x 30 mtr x 0.80					48 m ²
2 side x 20 mtr x 0.80					32 m ²
2 side x 10 mtr x 0.75					15 m ²

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
2 side x 25 mtr x 0.90 =					40 m ²
2 side x 30 mtr x $\left(\frac{0.80 + 0.70}{2}\right) =$					45 m ²
2 side x 22 mtr x 0.70 =					39.20 m ²
					219.20 m ²

(3) 15.3 (1)

Repair of Pot hole filled
with 75mm BMX 1.25' -

1 mtr x 1.20 mtr x 0.075 =					0.09 m ³
1.2 mtr x 0.8 mtr x 0.075 =					0.072 m ³
1 mtr x 1.5 mtr x 0.075 =					0.112 m ³
2 mtr x 1.5 mtr x 0.075 =					0.225 m ³
1.5 mtr x 1.5 mtr x 0.075 =					0.168 m ³

1.5 mtr x 1.5 mtr x 0.075 =					0.168 m ³
2 mtr x 2 mtr x 0.075 =					0.30 "
2.5 mtr x 8 mtr x 0.075 =					0.562 "
3 mtr x 2 mtr x 0.075 =					0.45 "
2 mtr x 2.5 mtr x 0.075 =					0.375 "
2 mtr x 2.5 mtr x 0.075 =					0.375 "
					2.90 m ³

(4) 15.3 (11)

Patch repairs over pot holes
with 90mm premix compact
with seal coat type R -

Qty vide this MR P-38

Item No: 15.3 (1)

2.90					38.67 m ²
0.075					

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(5) 15.3 (iii)					
Patch repairs over bituminous surface with 20mm Premix					
Qty vide this m/s P-38					
					Qty = 38.67 m ²
(8) 15.7 (ii)					
(9) 15.9.					
Maintenance of Road sign					
3.65 km of 15% = 0.10 km					
(10) 15.11					
Maintenance of 200m and km sign					
0.65 km of 18% = 0.12 km					
(11) 15.12					
(i) Cutting of branches of trees and shrubs					
(ii) - 2 No					
(ii) Cutting of shrubs from road way					
- 6 No					
(13) Maintenance of trees by the road side (Avenue trees) by mixing the soil with decayed farm yards					
					10 Nos

Abstract of Cost :-

40

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/W:- Construction of road from Teleniwa Jalapur Road to Paatibrik vidyalay Balua to Chadron Bazar Jala					
Name of Agency:- Kanchan Interprises					
Agg No:- 39/SBD/2021-22					
Date of started:- 15/01/22					
Date of Completion:- 14/05/22					
1) (15.1) Restoration of road ends/Banks with sand -- -- do -- etc.					
Qty vide this MB P- 37					
Qty = 46.05 m ³					
@ Rs 4042.06/m ³ --- Rs 186072.00					
(2) (15.2) Making up of Road/ shoulder, stripping excess soil from the shoulder -- -- do -- etc.					
Qty vide this MB P- 38					
Qty = 219.20 m ³					
@ Rs 602.81/m ³ --- Rs 132132.00					
(3) 15.3(1) Repair of pot holes filled with -- do -- 75mm BM X 1.28					
Qty vide this MB P- 38					
Qty = 9.90 m ³					
@ Rs 10848.78/m ³ --- Rs 314662.00					

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(4) (15-3) (ii)					
Patch repair over pot hole -					
res with 20 mm Premix carpet					
with seal coat type - n					
Qty vide this MB P-38					
Qty = 38.67 m ²					
@ R 821280 / m ² — 3 — R 1242520					
@ R 308279 / m ² — R 11941200					
5) 15-3 (iii)					
Patch repair over					
bitu m hours surface with					
20 mm Premix carpet with					
Qty vide this MB P-38					
Qty = 38.67 m ²					
@ R 321280 / m ² — R 12425200					
(9) 15-9.					
Maintenance of Road sign					
Qty vide this MB P-39					
Qty = 0.1 km					
@ R 110458 / km — R 108200					
(11) (15-12) (ii)					
cutting of shades from					
road sign — 6 No.					
Qty vide this MB P-39					
Qty = 6 No. @ R 6288 / c — R 42200					
(11) (15-12) (i)					

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Cutting of branches of trees and shrubs - 2 No.					
Qty = 2 No.					
@ Rs 113 = 99/e					Rs 228200
(13) Maintenance of trees by the road side (Avenue trees) by mixing - do - do - four years					
Qty = 10 No.					
@ Rs 410214/each					Rs 4101200
					Rs 92131200
Less (-) 22.01%					(-) 20269210
					7184220
					818h
					18/05/25
					82
add 12% h.s.r					(+) 8623=10
add 17% h.cus					(+) 719=00
					Rs. 81204200
					818h
					18/05/2025
					82
					82
					24/06/25
					EE