

4th year Maintenance

66

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/W:- Const. & Mainly of road From Taiyabpur talua to Bagmati Mirzapur.					
Agency:- Abdul barik.					
Agg. No:- 36 MHGSY/SBD/2019-20					
D.O.S:- 26-02-2020					
D.O.C:- 28-06-2021					
A.D.O.C:-					
Measurement.					
1) Restoration of raincuts.					
$6 \times 6.20 \times 0.90 \times 0.55 =$					19.90 m ³
$5 \times 4.20 \times 0.85 \times 0.45 =$					8.03 m ³
$6 \times 5.10 \times 1.00 \times 0.60 =$					18.36 m ³
$8 \times 4.20 \times 0.90 \times 0.60 =$					18.14 m ³
$6 \times 5.20 \times 1.00 \times 0.50 =$					12.95 m ³
$6 \times 5.00 \times 0.90 \times 0.60 =$					16.20 m ³
					93.58 m ³
2) Making up of Burm/shoulder					
$8 \times 9.00 \times 1.00 =$					72.00 m ²
$7 \times 8.50 \times 1.00 =$					59.50 m ²
$8 \times 8.00 \times 0.90 =$					57.60 m ²
$7 \times 8.50 \times 0.95 =$					56.52 m ²
$5 \times 7.90 \times 0.90 =$					35.55 m ²
$9 \times 5.00 \times 1.00 =$					45.00 m ²
					326.12 m ²
3) Repair to pot holes					
$4 \times 4.00 \times 1.00 =$					16.00 m ²
$3 \times 5.20 \times 0.95 =$					14.82 m ²
$5 \times 3.70 \times 0.95 =$					13.52 m ²

Continuation

	Abt. met. of work	
1)	Restoration of raincuds.	
	Qty vide M/B	
	page-66	98.58 m ³
	@ Rs- 386.14/m ³	Rs- 38066=00
2)	Making up of Burm/shoulder	
	Qty vide M/B	
	page-66	326.12 m ²
	@ Rs- 57.26/m ²	Rs- 18709=00
3)	Repair to pot holes	
	Qty vide M/B	
	page-67	67.67 m ²
	@ Rs- 384.28/m ²	Rs- 26004=00
4)	patch repair over pot holes	
	Qty vide M/B	
	page-67	67.67 m ²
	@ Rs- 284.15/m ²	Rs- 19229=00
	Continuation	

Scanned with CamScanner