

M.M.Gisy (S)

Locality - Logate Thanna - 6.329 km

Shedule XLV Form No. 134.

Executive Engineer PWD (W) Sharyadi DIVISION

A-E. PWD - Probation SUB-DIVISION

Aggr H. - 22.500/2001

Aggr Surveying & Survey

Measurement Book

Date of start - 28.7.21

Date of comp - 27.11.22

1362

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① First year maintenance Bill Restroom of Razaab/ Berms 48/9.501.					
	8x	1.75x	0.8x	0.36x	3.36m ²
	16x	2.4x	0.8x	0.36x	7.68m ²
					11.04m ²
② Making up of berms / shoulders stoping excess					
	24x	1.50x	0.9x		32.40m ²
	12x	2.4x	0.8x		19.20m ²
	7x	2.25x	0.65x		10.24m ²
					61.84m ²
③ Repair of patches filled w/15.75mm					
	2x	0.4x	0.4x	0.25x	0.02m ²
④ Patch repair over pot holes w/15. 20mm premix					
	8x	0.4x	0.4x		0.32m ²
	16x	0.6x	0.5x		4.80m ²
					5.12m ²
⑤ Patch repair over bituminous surface w/15.20mm premix					
	12x	0.65x	0.65x		5.07m ²

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	x D.	
(6) Paving of concrete and joints including Circumferential encasing					
	28	21.50			= 42.00 m ²
	49	2.0			= 98.00 m ²
	64	1.25			= 80.00 m ²
					<u>220.00 m²</u>
(7) Repair of isolated area & damaged Concrete Pavement					
	16	0.35	20.35		= 1.36 m ²
	48	7.0	45.00	4.50	= 9.72 m ²
	84	1.00	11.00		= 11.60 m ²
(8) Removal of existing Sealant and resealing of Chippings					
	127	12.7	3.75		= 47.62 m ²
(9) Maintenance of C/D works (House pipe)					
	16	2			= 2.00 m ²
(10) Maintenance of Road sign					
					= 0.725 m ²

Continuation

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	Restoration of C&D				
	(All City and THB)				
(1/1)	Restoration of Rainwater				
	Berms with 5:1				
	Page No. - (52) = 11.0418				
	@ Rs 386.14/m ² Rs 4263 =				
(2/2)	making up of				
	berms shoulder				
	Page No. - (52) = 61.8411				
	@ Rs 571.36/m ² Rs 3547 =				
(3/3)	Repair of Potholes				
	filled with 75MM				
	Page No. - (52) = 0.0218				
	@ Rs 9650.18/m ³ Rs 193 =				
(4/4)	Patch repair over				
	potholes with 75MM				
	Page No. - (52) = 5.1211				
	@ Rs 245.35/m ² Rs 1259 =				
(5/5)	Patch repair over				
	Bituminous surface				
	Page No. - (52) = 5.0211				
	@ Rs 262.62/m ² Rs 1331 =				

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(6/6) Filling of cracks and joints including page No. (53) = 220.04 @ Rs 379/m Rs 834 =					
(7/8) Repair of isolated areas of damaged concrete page No. (52) = 11.684 @ Rs 245.95/m Rs 2873 =					
(8/9) Removal of old Bitum sealant and renewal page No. (52) = 476.254 @ Rs 23.48/m Rs 11182 =					
(9/11) Maintenance of C/P works (Hume pipe Culverts) page No. (53) = 2.044 @ Rs 1130.62 each Rs 2261 =					
(10/12) Maintenance of Road signs page No. (53) = 0.729 km @ Rs 1077.81/km Rs 787 =					
(11/15) Maintenance of 2-churnston 2 KH 450					

16/4/25
E

AT 6/9/13