

MMGSY(SC) - Nagma Jainagar Road to Jagiya
Ag. No - 11 SBD/22-23
Schedule XLV-Form No. 134

Ag. Value - Rs. 96,05,100/-

Sheeghat

DIVISION

Gurua

SUB-DIVISION

M/S Maa Shanti Const.

MEASUREMENT BOOK

14/1

Continuation

Particulars	Details of actual measurement			Contents of area
	No.	L	B	
			12/14/22	
3 15.5.10	Repair of pot holes filled with 25mm wgn. do also.			
				$2 \times 1.00 \times 1.00 \times 0.075 = 0.150 \text{ m}^3$
4 15.5.11	Patch repair over Bituminous surface with 20mm primix Carpet. do also.			
				$2 \times 1.00 \times 1.00 = 2 \text{ m}^2$
				$2 \times 20 \times 0.60 = 24 \text{ m}^2$
				$15 \times 2.00 \times 0.75 = 22.5 \text{ m}^2$
				$T = 48.5 \text{ m}^2$
5 15.5.11	patch repair over Bituminous surface with 20mm M 35. do also			
				$2 \times 1.00 \times 1.00 = 2 \text{ m}^2$
				$20 \times 2.00 \times 0.60 = 24 \text{ m}^2$
				$15 \times 2.00 \times 0.75 = 22.5 \text{ m}^2$
				$T = 48.5 \text{ m}^2$
6 20.10.6	Crack sealing of crack and joint excluding do also			
				$1035 \times 1 = 1035 \text{ m}$
7 20.10.7	Repair of concrete pavement isolated areas do also			
				$11 \times 3.0 \times 0.60 = 19.8 \text{ m}^2$
				$\text{Kmt} = 19.61 \text{ m}^2$
8 20.10.10	Repair of old joint sealant do also			
				$1 \times 380 \text{ m} = 380 \text{ m}$

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>9</u> 15.7-1	Repair of H.P. cut along of Nax				
<u>10</u> 15.7	Repair of Road edge along 1.440 km				
<u>11</u> 15.11	Repair of 200 M & K.M. along 1.440 km				
<u>12</u> 15.12(1)	Cutting of Branches of trees of Nax				
<u>13</u> 15.12.11	Cutting of Shrub from Roadway along 1035 Nax				
<u>14</u> 15.12.11	Turning of green R. waste				
		2 x 10 x 30 x 1.00 =	600 m ²		
		2 x 10 x 30 x 1.00 =	600 m ²		
		2 x 10 x 30 x 1.00 =	600 m ²		
		2 x 9 x 30 x 1.00 =	540 m ²		
			2340 m ²		
			Int 2329 m ²		
<u>15</u> 15.12	White washing of perimeter of C.D. along				
		2 x 3.60 x 0.40 =	2.88 m ²		
		4 x 0.40 x 0.60 =	0.96 m ²		
		2 x 3.60 x 0.60 =	4.32 m ²		
			T = 8.16 m ²		
		8 x 5 x 8.16 m ² =	40.8 m ²		

Continuation
AE 50/6/15

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L	B.	D.	
				3.83	
6.10.16 Crack sealing					
filling of cracks do					
Qty vide TMBP.59					
item no 6					
1035 m @ 3.83/m					= 3964 sq m
7.10.16 Repair of concrete					
parapet isolated do					
Area do do					
Qty vide TMBP.59					
item no 7					
19.01 m ² @ 253.10/m ²					= 4811 sq m
8.10.16 Repair of joint					
sealant do do					
Qty vide TMBP.59					
item no 8					
390 m @ 23.49/m					= 8926 sq m
9.15.2(1) Repair of Hp culvert					
Qty vide TMBP.60					
item no 9					
05 Nos @ 1130.62/each					= 5653 sq m
10.15.9 Repair of road sign					
Qty vide TMBP.60					
item no 10					
1.440 km @ 1072.91/km					= 1552 sq m
11.15.11 Repair of 200m x 10m drain					
Qty vide TMBP.60/11					
1.440 km @ 628.22/km					= 905 sq m
					T= 98148 sq m

Continuation

Continuation
A6 30/6/85