

Details of AA

AA vide letter No 350315 (3103) 4515-01-80/2025-357
UDOT dated - 14/02/25

Cost of initial Rectification & surface renewal	₹ 20.567 lac
6 yrs operation & management	₹ 1.429 lac
emergency & Price Adjustment cost	₹ 3.299 lac
Contingency & Administrative fund	₹ 0.715 lac
	<u>₹ 26.010 lac</u>

Details of T.S

Construction cost	₹ 21.161 lac
6 yrs operation & management cost	₹ 1.427 lac
Contingency @ 1%.	₹ 0.226 "
Administrative fund @ 2.5%.	₹ 0.508 "
	<u>23.322 lac</u>

Technically sanctioned for Rs. 23.322 lac
(Rupees ~~twenty~~ three lac thirty two thousand two hundred only)

certified copy

R 28/2/25
Superintending Engineer
Rural Works Department
Works Circle, Saharsa

~~Superintending Engineer
Rural Works Department
Works Circle, Saharsa~~

sd
Superintending Engineer
Rural Works Department
Works Circle, Saharsa