



कार्यपालक अभियन्ता का कार्यालय
ग्रामीण कार्य विभाग , कार्य प्रमण्डल राजगीर (नालन्दा)

Email:- rwdrajgir@gmail.com, ee.rajgir@rwdbihar.in

पत्रांक.....503(अमृ०)

राजगीर

दिनांक...14-06-2025

प्रेषक,

कार्यपालक अभियन्ता
ग्रामीण कार्य विभाग
कार्य प्रमण्डल राजगीर।

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव,
ग्रामीण कार्य विभाग,
पटना।

विषय:- नई अनुरक्षण नीति 2018 शीर्ष MR-3054 योजना मद अन्तर्गत व्यय हेतु आवंटन की माँग के
संबंध में।

महा तय,

उपर्युक्त विषयक नई अनुरक्षण नीति 2018 शीर्ष MR-3054 योजना मद अन्तर्गत व्यय हेतु विहित
प्रपत्र में अधियाचना पत्र संलग्न कर भेजी जा रही है।

अतः अनुरोध है कि संलग्न विवरणी के अनुसार आवंटन उपलब्ध कराने की कृपा की जाय। ताकि
कराये गये कार्यों का भुगतान किया जा सके। संबंधित संवेदक का इस प्रमण्डल में कोई ATR लम्बित नहीं
है।

अनु०:- यथोक्त।

विश्वासभाजन

कार्यपालक अभियन्ता
ग्रामीण कार्य विभाग
कार्य प्रमण्डल राजगीर

13/06/25

FORM GFR 19-A

(See Government of India's Decision(I) below Rule-150)
Utilisation Certificate upto the month of May- 2025

MR(3054) New Maintainance Policy 2018

STATE - BIHAR

Sl. No.	Name of Scheme	Sanction No. & Date with Amount (In Rs. Lacs)	Amount Received (In Lacs)	Particulars
1	MR(3054) New Maintainance Policy 2018	Letter No.-45 Date-27.05.2025	6334.72748	Certified that out of 6334.72748 Laacs of grants-in-aid sanctioned during the years 2020-21, 2021-22, 2022-2023, 2023-24, 2024-25 & 2025-26 in favour of E-in-C, RWD Bihar, Patna a sum of Rs 6296.59106 been utilized for the purpose of MR(3054) New Maintainance Policy 2018 and Rs. 20.28866 has been surrender as given in the margin for which it was sanctioned and the balance of Rs 38.13642 remaining unutilized at the end of the period under.
		Total	6334.72748	

- 2 Certified that I have satisfied my self that the conditions on which the gran.s-in-aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned

Kind of Checks exercised :-

- (i) Works have been supervised by Executive Engineer/ Superintending Engineer.
 - (ii) Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
 - (iii) Construction materials have been tested.
Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer./ Executive Engineer.
 - (iv) Executive Engineer.
 - (v) All other codal formalities have been observed.
- 3 Physical Progress achieved :-
- (i) Construction of Road Works
 - (ii) Construction of CD works


Executive Engineer
RWD, Works Division
Rajgir (Nalanda)
14/6/25


Requisition Format for scheme Head : MR(3054) Under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

RWD, Works Division : Rajgir																
Requisition Format for scheme Head : 1000																

1 Signed Hard Copy and Soft Copy (In Excel) of recorded IRI is enclosed.
2 Up-to date Physical Progress has been uploaded in MIS

13/10/2025
14/10/25
Executive Engineer
RWD (W) Division Rajgir

File :E:\Office\Allotment Requestion\Bump Report\vijay sngh\25091395-.xlsx Section No.:18, Egn :test
 Name of Customer :VIJAY KUMAR SINGH, Name of Work/ Road :L024-Silao - Bhui Road to Milkiper Rural Road ,



30/5/25
 30/5/25
 30/5/25

30/5/25
 30/5/25
 30/5/25

30/5/25
 30/5/25
 30/5/25

Executive Engineer
 RWD (W) Div. Rajgarh
 30/5/25

Contractor Name :- Vijay Kumar Singh

Date	Time	Section	Length	Bumps	Speed	OR	IRI	CATEGORY	Latitude	Longitude	Event
30/05/25	17:18:9		18	0.1	200	10.1	2000	2404 G	25.067292	85.067292	Normal
30/05/25	17:19:0		18	0.1	190	20.2	1900	2290 G	25.06806	85.390985	Speed Breaker
30/05/25	17:19:20		18	0.1	230	30.3	2300	2745 G	25.068281	85.390391	Speed Breaker
30/05/25	17:20:0		18	0.1	250	20.2	2500	2972 G	25.068987	85.390633	Culvert
30/05/25	17:20:0		18	0.1	270	20.2	2700	3199 G	25.070025	85.388663	Normal
30/05/25	17:20:30		18	0.1	100	40.4	1000	1268 G	25.07478	8.389365	Normal
30/05/25	17:20:30		18	0.1	120	40.4	1200	1495 G	25.077647	85.389662	Culvert
30/05/25	17:21:6		18	0.1	240	10.1	2400	2858 G	25.088682	85.388646	Normal
30/05/25	17:21:41		18	0.1	220	10.1	2200	2631 G	25.069155	85.387857	Normal
30/05/25	17:22:0		18	0.1	270	20.2	2700	3199 G	25.069839	85.388168	Culvert
30/05/25	17:22:16		18	0.1	250	20.2	2500	2972 G	25.073856	85.389065	Normal
30/05/25	17:22:16		18	0.1	320	20.2	3200	3767 G	25.075922	85.38963	Normal
30/05/25	17:22:16		18	0.1	230	20.2	2300	2745 G	25.076198	85.389817	Normal
30/05/25	17:23:0		18	0.1	220	10.1	2200	2631 G	25.07753	85.389624	Speed Breaker
30/05/25	17:24:0		18	0.1	320	20.2	3200	3767 G	25.078096	85.38905	Speed Breaker
30/05/25	17:24:2		18	0.1	300	10.1	3000	3540 G	25.079225	85.387834	Normal
30/05/25	17:36:0		18	0.1	120	40.4	1200	1495 G	25.079247	85.387812	Culvert
30/05/25	17:36:17		18	0.1	270	10.1	2700	3199 G	25.07929	85.387603	Normal
30/05/25	17:40:36		18	0.1	320	20.2	3200	3767 G	25.079628	85.387305	Normal
30/05/25	17:42:32		18	0.1	150	30.3	1500	1836 G	25.080407	85.387233	Normal
30/05/25	17:42:32		18	0.1	250	20.2	2500	2972 G	25.08066	85.388688	Culvert
30/05/25	17:42:36		18	0.1	150	30.3	1500	1836 G	25.08067	85.387538	Normal
30/05/25	17:45:48		18	0.1	270	20.2	2700	3199 G	25.080683	85.387784	Culvert
30/05/25	17:46:02		18	0.1	230	30.3	2300	2745 G	25.08066	85.388688	Normal
30/05/25	17:46:56		18	0.1	100	30.3	1000	1268 G	25.081035	85.389109	Normal

AVG
2672

(R) RURAL ROAD	
Good	Poor
4001-5000	>5001

~~Handwritten signature~~
30/05/15
ZE

Answer -

Executive Engineer,
RWD (W) Div. Rajgir