

Schedule XLV-Form No. 134

पञ्चहरि बहामन बहिराय बहान बहरी
राय गहोन

मसकामलेश्वर रा DIVISION

ब्लक-हरिहर SUB-DIVISION

1
ममस्य-न.त.ब

MEASUREMENT BOOK

MB-2-407

1st Year Maintenance

47

Sch. XLV-Form No. 134

[illegible]

1) Restoration of Raincatch/ Berms			
	with soil-		
6x4.50x	0.90=	21.30	24.30
2x5.50x	0.90=	19.80	
2x3.00x	0.90=	25.40	
2x5.00x	0.90=	32.76	
3x2.25x	0.90=	6.07	
		106.33M ²	
		31.35m	
106.33x0.30	=		31.90M ³
2) Making up of Berms/shoulder,			
stripping excess soil -			
2x1x15x	0.90=	27.00	
2x1x19x	0.90=	34.20	
2x1x25x	0.80=	40.00	

Continuation

Continuation

Continuation