

5th Year Maintenance Work

Sch. XLV-Form No 134

47

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of Work = Maintenance of road from Palte Belwa Chinni to Madhopur Govind via Raskiya Buniyadi vidyalaya under MM4SY.					
Agency = Suted Builders.					
India Pvt Ltd.					
Agreement no - 78 SBD / 2018 - 19.					
Date of work order - 09-03-2019.					
Contract date of completion - 08-03-2020.					
Actual date of completion - 07-03-2020.					
Period of 5th Year Maintenance					
08-03-2024 to 07-03-2025.					

Routine Maintenance work has been done by the Agency during above Maintain Period Measurement of Work.

① Restoration of rain cuts.

1X	18.26X	1.25X	0.30 =	6.84 m ³
1X	13.69X	1.22X	0.30 =	5.01 m ³
1X	23.15X	1.20X	0.30 =	8.33 m ³
1X	16.81X	1.21X	0.25 =	5.08 m ³
1X	11.55X	1.18X	0.25 =	3.41 m ³
2X	10.15X	1.15X	0.25 =	5.83 m ³
1X	19.50X	1.22X	0.30 =	7.14 m ³
3X	8.50X	1.15X	0.25 =	7.33 m ³
1X	19.10X	1.18X	0.25 =	5.63 m ³
7X	4.50X	1.15X	0.25 =	9.05 m ³

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	2X	5X	25X	0.10	25m ²
	2X	2X	25X	0.10	10m ²
	Total				320m ²

~~15/06/2015~~
15/06/2015

~~10/06/2015~~
10/06/2015

~~10/06/2015~~
10/06/2015

Abstract of Cost

① Restoration of rain cuts

Quinty vide TMBP - 47

78.95m³ @ Rs 378.32/m³ Rs = 29868 = ∞

② Maintenance of earthen shoulder.

Quinty vide TMBP - 48

312.19m² @ Rs 57.35/m² Rs = 17904 = ∞

③ Repair of pot holes by removal of faked materials

Quinty vide TMBP - 48

74.59m² @ Rs 286.16/m² Rs = 21344 = ∞

④ Maintenance of worn road including filling up of pot holes.

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	2X	5X	25X	0.10 =	25m ²
	2X	2X	25X	0.10 =	10m ²
				Total	320m ²




[Signature]
15/06/2025
BZ

[Signature]
10/06/25
J.E

[Signature]
10/06/25
(T.S)

Abstract of Cont

- ① Restoration of rain cuts
 Qty. vide TMBP-47
 $78.95 \text{ m}^3 @ \text{Rs } 378.32 / \text{m}^3 \text{ Rs} = 29868 = \infty$
- ② Maintenance of earthen
 shoulder.
 Qty. vide TMBP-48
 $312.19 \text{ m}^2 @ \text{Rs } 57.35 / \text{m}^2 \text{ Rs} = 17904 = \infty$
- ③ Repair of pot holes by
 removal of failed materials
 Qty. vide TMBP-48
 $74.58 \text{ m}^2 @ \text{Rs } 286.16 / \text{m}^2 \text{ Rs} = 21344 = \infty$
- ④ Maintenance of worn road
 including filling up of
 pot holes.

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Qunty. vide TMBP - 49					
74.59/m ² @ Rs 362.37/m ² Rs = 27029=00					
⑤ Patch repair on already filled pot-holes.					
Qunty. vide TMBP - 49					
74.59/m ² @ Rs 270.56/m ² Rs = 20181=00					
⑥ Maintenance of lime Pipe Culvert.					
Qunty. vide TMBP - 49					
1 Nos @ Rs 1109.67 = 1110=00					
⑦ Maintenance of road Signs					
Qunty - vide TMBP - 49					
3,901 CM @ Rs 104.51 = 3200=00					
⑧ Providing and applying 2 Coats of Water based Cement Paint.					
Qunty vide TMBP - 49					
180 m ² @ Rs 102.88/m ² Rs = 18518=00					
⑨ Providing & laying of hot applied thermoplastic					
Qunty. vide TMBP - 49.					
320 m ² @ Rs 850.82/m ² Rs = 272294=00					
TOTAL Rs = 411448=00					
Less 0.25% below (-) Rs = 1028=00					
Rs = 410420=00					
 J. S. Choudhary 15/06/2015 Continuation  J. S. Choudhary 15/06/2015  J. S. Choudhary 15/06/2015					