

# 4<sup>th</sup> year maintenance Bill

47

Sch. XLV—Form No. 134

| Particulars                                    | Details of actual measurement |             |      |                       | Contents of area |
|------------------------------------------------|-------------------------------|-------------|------|-----------------------|------------------|
|                                                | No.                           | L.          | B.   | D.                    |                  |
| Name of Road:- maintenance of Road from NH 30A |                               |             |      |                       |                  |
| Gadambura Road To Kharijama Mahadalit Rd.      |                               |             |      |                       |                  |
| Agency:- Tai maa Construction                  |                               |             |      |                       |                  |
| Agreement no:- 28/SBD/2018-19                  |                               |             |      |                       |                  |
| Date of Commencement:- 20/07/18                |                               |             |      |                       |                  |
| Date of Completion:- 16/04/19.                 |                               |             |      |                       |                  |
| Date of entry:-                                |                               |             |      |                       |                  |
| ITEMS                                          |                               |             |      |                       |                  |
| ① Restoration of Raincuts                      |                               |             |      |                       |                  |
| Do                                             | Do                            |             |      | 61                    |                  |
|                                                | 8 X 5                         | 1.0 X 1.20  | 0.30 | 8.92 m <sup>3</sup>   |                  |
|                                                | 9 X 6                         | 1.50 X 1.10 | 0.30 | 19.30 m <sup>3</sup>  |                  |
|                                                | 10 X 3                        | 1.50 X 1.20 | 0.30 | 12.60 m <sup>3</sup>  |                  |
|                                                | 12 X 2                        | 2.50 X 1.15 | 0.30 | 10.35 m <sup>3</sup>  |                  |
|                                                | 18 X 1                        | 1.90 X 1.20 | 0.30 | 12.31 m <sup>3</sup>  |                  |
|                                                | 16 X 1                        | 1.80 X 1.20 | 0.30 | 10.36 m <sup>3</sup>  |                  |
|                                                | 4 X 5                         | 1.10 X 1.20 | 0.30 | 7.34 m <sup>3</sup>   |                  |
|                                                |                               |             |      | 81.18 m <sup>3</sup>  |                  |
| ② Maintenance of earthen Shoulder.             |                               |             |      |                       |                  |
| Do                                             | Do                            |             |      | 61                    |                  |
|                                                | 2 X 20                        | 1.20 X 1.20 |      | 86.40 m <sup>2</sup>  |                  |
|                                                | 2 X 14                        | 1.60 X 1.20 |      | 53.76 m <sup>2</sup>  |                  |
|                                                | 2 X 11                        | 1.80 X 1.20 |      | 39.60 m <sup>2</sup>  |                  |
|                                                | 2 X 12                        | 1.90 X 1.20 |      | 54.72 m <sup>2</sup>  |                  |
|                                                | 2 X 16                        | 1.85 X 1.20 |      | 71.04 m <sup>2</sup>  |                  |
|                                                |                               |             |      | 305.52 m <sup>2</sup> |                  |
| ③ Repair of Pot holes filled.                  |                               |             |      |                       |                  |
| Do                                             | Do                            |             |      | 61                    |                  |
|                                                | 8 X 2                         | 50 X 0.90   |      | 18.00 m <sup>2</sup>  |                  |

Continuation

| Particulars                         | Details of actual measurement |                            |    |    | Contents of area |
|-------------------------------------|-------------------------------|----------------------------|----|----|------------------|
|                                     | No.                           | L.                         | B. | D. |                  |
| 73.28m <sup>2</sup>                 |                               | VTMBP-48                   |    |    |                  |
|                                     |                               | @ Rs 197.83/m <sup>2</sup> |    |    |                  |
|                                     |                               |                            |    | Rs | 14497.00         |
| 3) Maintenance of H.P Culvert       |                               |                            |    |    |                  |
| Do                                  | Do                            | Do                         | Do | Rs |                  |
| 1.00 No                             |                               | VTMBP-48                   |    |    |                  |
|                                     |                               | @ Rs 1104.35/No            |    |    |                  |
|                                     |                               |                            |    | Rs | 1104.00          |
| 7) Maintenance of slab Culvert      |                               |                            |    |    |                  |
| Do                                  | Do                            | Do                         | Do | Rs |                  |
| 1.00 No                             |                               | VTMBP-48                   |    |    |                  |
|                                     |                               | @ Rs 2287.21/No            |    |    |                  |
|                                     |                               |                            |    | Rs | 2287.00          |
| 8) Maintenance of Road Sign         |                               |                            |    |    |                  |
| Do                                  | Do                            | Do                         | Do | Rs |                  |
| 0.16 km                             |                               | VTMBP-48                   |    |    |                  |
|                                     |                               | @ Rs 1067.44/km            |    |    |                  |
|                                     |                               |                            |    | Rs | 171.00           |
| 8) Maintenance of 200 m & km stones |                               |                            |    |    |                  |
| Do                                  | Do                            | Do                         | Do | Rs |                  |
| 0.19 km                             |                               | VTMBP-48                   |    |    |                  |
|                                     |                               | @ Rs 569.27/km             |    |    |                  |
|                                     |                               |                            |    | Rs | 109.00           |
| 9) Cutting of branches of trees     |                               |                            |    |    |                  |
| Do                                  | Do                            | Do                         | Do | Rs |                  |
| 2.00 No                             |                               | VTMBP-48                   |    |    |                  |
|                                     |                               | @ Rs 104.48/No             |    |    |                  |
|                                     |                               |                            |    | Rs | 209.00           |
| 10) White washing of Picket Walls   |                               |                            |    |    |                  |
| Do                                  | Do                            | Do                         | Do | Rs |                  |
| 21.00 m <sup>2</sup>                |                               | VTMBP-48, 49.              |    |    |                  |
|                                     |                               | @ Rs 15.65/m <sup>2</sup>  |    |    |                  |
|                                     |                               |                            |    | Rs | 329.00           |
|                                     |                               |                            |    | Rs | 79879.00         |
| Less 0.05% Below Rs Per Agreement   |                               |                            |    | Rs | 40.00            |
|                                     |                               |                            |    | Rs | 79839.00         |

Continuation

For  
20-7-23

17/4/23  
A.E.

For  
17/4/23  
J.E.