

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
5 th year maintenance B.I.					
x Name of work: - Const of Road					
from 104 to Sahy 1019					
- Agency - Shahbaz Anwar					
Aggr. No:- 25/SB0/2018-19					
Date of Commencement:- 21/04/2018					
Actual date of Comp:- 20/4/2019					
Actual date of Comp:- 25/03/2020					
Rate - 10% Comp below					
Record entry					
1) Restoration of Rain cuts					
with Soil 10084 m					
$4 \times 30 \times 2 \times 1.125 \times 0.30 = 81.00 \text{ m}^3$					
$1 \times 21 \times 2 \times 1.125 \times 0.30 = 14.175 \text{ m}^3$					
					95.175 m ³
2) Shaking up Berms / shoulder					
8th bar in center Soil from surface					
$3 \times 30 \times 2 \times 1.125 = 202.5 \text{ m}^3$					
$3 \times 30 \times 2 \times 1.125 = 202.5$					
$3 \times 20 \times 2 \times 1.125 = 135$					
					540 m ³
3) P-30					
Gravelled to = 539 m ³					

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>Abstract of C&F.</u>					
1) Restoration of Rain cut vide TmbP - (60)					
95.00m ³ @ 358.87 = 34042.00					
2) making up Berms / shoulder stripping excess soil vide TmbP - (60)					
539m ³ @ 54.16 = 29192.00					
3) Repair of pot hole with 75mm Bm, vide TmbP - 6.28m ³ @ 10687.98 = 67165.00					
4) Patch Repair over pot holes with surface dressing vide TmbP - (61) 83.74m ² @ 120.25 = 10075.00					
5) Patch Repair over bituminous surface over surface dressing P - (62) 83.74m ² @ 107.50 = 9007.00					
6) man of downing of curb vide TmbP - (62) 2 nos @ 1067.89 = 2135.00					
7) man of downing of curb curb					

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	

2 Nos. Vicar Timber - 6

3 Nos. @ 2200 cr = 6600.00

total = 158,286.00

Cen - 10% Belav = 15828.60

142457.40

[Signature]
18/01/21
BB

योजना

o Sa

Tola

T01

an T

ar M

ool

uslin

hura

Mus

a

मूल
के ये ग