



Abstract of Cost

1st Year Maintenance

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(1) Restoration of Rain cuts					
Qty vide 2013 PM-30					
Q = 38.48 m ³ @ 394.20/m ³					15168.00
(2/2) making up of berms/shoulder.					
Qty vide 2013 PM-30					
Q = 442.37 m ² @ 58.92/m ²					26122.00
(2/5) patch Repair bitumen surface.					
Qty vide 2013 PM-30					
Q = 17.81 m ² @ 236.30/m ²					4208.00
(4/9) maint. of Road Sign.					
Qty vide 2013 PM-30					
Q = 0.16 km @ 1077.82/km					172.00
(4/10) maint. of road sign					
Qty vide 2013 PM-30					
Q = 0.19 km @ 570.89/km					108.00
(4/11) cutting of branch of tree					
Qty vide 2013 PM-30					
Q = 2 nos @ 109.74/no					219.00
Total = 45997.00					
Add 184.00 = 8279.00					
14.60 = 460.00					
5 fee = 919.00					
Total = 55,655.00					
less 0.21% (117.00)					
Net = 55,538.00					
 2013  2013					
Continuation					
02/11/23					

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	

makul & fatant					
----------------	--	--	--	--	--

E/w - 82.78 m ³ @ 35.25					
------------------------------------	--	--	--	--	--

chips - 0.5 m ³ @ 553.32					
-------------------------------------	--	--	--	--	--

Birch - 33 by					
---------------	--	--	--	--	--

[Signature]
20/12/25
[Signature]