

REO Path Lakshmi Asthan to ISLam ron house

Total Length - 3.70 K.M

Schedule XLV Form No. 134.

MMSY(HB).

RWD HD BIJIPUR

DIVISION

BASANTPUR

SUB-DIVISION

Gobind Kumar

PZ NO- 43 / SBD/ 2019-20.

Measurement Book

730
Sect 11

Name of work -

Situation of work -

Agency by which work is executed -

Date of measurement -

No. and date of agreement.

(These four lines should be repeated at the commencement
of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work -					
Road from RFD path Lakshmi					
Asthan to Bhangu railway house					
Total length -	3.700	K.M			
Block - Basantpur (Supaul)					
Scheme under - MMBSSY (WB) 2019-2020					
Name of Agency - Govind Kumar					
Agreement No - SBD/2020-2021					

(A) Construction Cost	Rs 295,40,25/-
(B) 5 year Maintenance Cost	Rs 34,82,596/-
Total Agreement Amount	Rs 329,72,855/-
Date of Start -	
Date of Completion	
Date of Measurement	12/01/2020

(1) Construction of Reference	
Bench mark etc under all cups	= 4.00 Nos
Mitters etc under all cups	= 1.30 Nos
pillars etc under all	= 15.00 Nos
(2) Construction of Reference	
pillars etc under all	= 15.00 Nos
(3) Clearing and levelling	
'Continuation'	

4th year maintenance area

65

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/W =) Reo path Langtang Aetham					
to Bhangu person House —					
Agency — Oxfam International					
Agreement No: — 43 S82 2090-21					
Actual date of completion — 29/12/20					
Record entry					
① Restoration of paintwork /					
Berming					
$2 \times 25 \times 6.0 \times 1.50 \times 0.300 \Rightarrow 135.0 m^3$					
$2 \times 30 \times 7.60 \times 1.50 \times 0.300 \Rightarrow 164.4 m^3$					
299.16 m ³					
② Making up Berming / shoulders					
excuse loil —					
$2 \times 30 \times 2 \times 1.5 \Rightarrow 180.0 m^3$					
$2 \times 40 \times 9.1 \times 1.30 \Rightarrow 946.4 m^3$					
1666.40 m ³					
@ reinit $\Rightarrow 1665.0 m^3$					
③ Repair not holes fixed					
with 150mm 9.0 —					
$20 \times 5.5 \times 2.5 \times 0.075 \Rightarrow 20.62 m^3$					

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>ABSTRACT OF COST</u>					
(1) Restoration of Pavement / Berm —					
THB P - 65 qtr - 299.16 m ³ @ 380.89/m ³ ⇒ 113947.00					
(2) Marking up of Berm —					
THB P - 65 qtr - 1665.0 m ² 54.01/m ² ⇒ 94921.00					
(3) Repair of pot holes filled 78 mm —					
THB P - 65 qtr - 90.62 m ³ @ 11096.68/m ³ ⇒ 228813.00					
(4) Patch repair of pot holes with seal —					
THB P - 65 qtr - 248.0 m ² @ 284.20/m ² ⇒ 78155.00					
(5) Maintenance of H.P culvert —					
THB P - 66 qtr - 6.00 m ³ @ 1106.59/m ³ ⇒ 6639.00					
(6) Maintenance of slab culvert —					
THB P - 66 qtr - 2.00 m ³ @ 2281.27/m ³ ⇒ 4562.00					
Continuation				<u>827034.00</u>	

Sch. XLV-Form No. 134 *gfp 12824637-00*

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(9) Maintenance of Road sign —	THSP- 66	PH - 3.70 m			
	@ 1094.06/m \Rightarrow	4648.00			
(8) Maintenance of road post —	THSP- 66	PH - 3.70 m			
	@ 123.67/m \Rightarrow	2307.00			
(9) cutting of branches at tree —	THSP- 66	PH - 6.00 m			
	@ 106.48/m \Rightarrow	638.00			
(10) cutting of shrubs from roadway —	THSP- 66	PH - 30.00 m			
	@ 6.54/m \Rightarrow	196.60			
(11) white washing of parapet wall —	THSP- 66	PH - 126.00 m			
	@ 16.09/m \Rightarrow	2024.00			
					836253.00
	@ Ad 12.1.65 \Rightarrow	64350.00			
	@ Ad 1.1.1.6 \Rightarrow	8362.00			
					605765.00
1000000	1000000	1000000	1000000	1000000	