

Name of work - Madhwa Bidyalay Akbarpur Bank village
to Haritara stola Satahi Chhat

Schedule XLV-Form No -134

AKBARPUR BANK

M.M. G.S.J.
~~AKBAR~~ SC

B/maral

DIVISION

DT 482300

Subrail

SUB-DIVISION

Ag. No - 74/5.B.D/17-18

Memo - 887

MEASUREMENT BOOK

M. PARVEET ALAM

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>Abstract of cost</u>					
① Restoration of Reincuts					
P/70					104.00 m ³
					@ 358.87 = 37322/-
② Stripping excess soil					
P/71					577.97 m ²
					@ 54.16 = 31308/-
③ Pr. Patch Repair of Foot path					
P/71					47.54 m ²
					@ 112.45 = 5346/-
④ Pr. Patch Repair of B.T Surface					
P/72					48.16 m ²
					@ 100.92 = 4860/-
⑤ Maintenance of H.P. culvert					
P/72					04 Nos
					@ 1067.89 = 4272/-
⑥ Maintenance of Slab culvert					
P/72					04 Nos
					@ 2200.02 = 8800/-

Continuation

