

पेंटगत बिराज पन्था ते क्हातवे तो १ रुपया (ममूस्य-ग्रेन)

Schedule XLV-Form No. 134

DIVISION

पेठगाव

SUB-DIVISION

पेठगाव

MEASUREMENT BOOK

1622

पेठगाव कृष्ण रेवत

4th Year Maintenance Bill

Sch.XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of land - Main house and of					
Recd from private person					
Khata - of Revenue under Munsif (Uch)					
Agency - Govt. Munsif Kharan Fort					
Ag. No - 415 BD/ 2019 - 20					
Date of Enment - 26.11.2019					
Actual date of completion - 20.02.2021					
Date of Measurement -					
① Restoration of damaged / repairs					
with soil smoothing etc as per E/D					
	2x30x1.2	0.50	10.80		
	6x30x1.2	0.50	36.00		

	6x12x1.2	0.30	21.60		
	4x15x1.2	0.30	18.00		
			130.50		
Total - 130.49					

② Making up Repair/shoulder,					
stripping excess soil from the					
shoulder surface to achieve level					
etc as per E/D					
	2x15x1.2		3.60		
	2x3x15x1.2		7.20		
	5x15x1.2		9.00		
	2x7.5x1.2		2.25		
	4x15x1.2		7.20		
	3x15x1.2		5.40		
	6x7.5x1.2		7.20		

Continuation

Sch.XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Recovery of cost					
② Rectification of Faintness/Roads with soil 1000mm 95 per E/I					
at V.T.M.B.P. - (46)					
130.49m ² @ 380.52/m ² = 49662m					
③ Making up Road/Sidewalk, cutting excess soil from the shoulder surface to achieve 1000mm 95 per E/I					
at V.T.M.B.P. - (47)					
770.21m ² @ 59.37/m ² = 45960.00					
④ Repair of pot holes filled with 75mm RM 95 per E/I					
at V.T.M.B.P. - (48)					
11.33m ² @ 11654.19/m ² = 132011.00					
④ Patch Repair over pot holes in bit seal surface 95 per E/I					
at V.T.M.B.P. - (47)					
1510.3m ² @ 299.14/m ² = 45179.00					
⑤ Maintenance of C/P with C.H.P. curbs 95 per E/I					
at V.T.M.B.P. - (42)					
3m ² @ 1117/m ² = 3351.00					

Continuation

51.

Continuation