

# 1st year maint

39

Sch.XLV-Form No. 134

| Particulars                      | Details of actual measure |    |    |      | Contents of area     |
|----------------------------------|---------------------------|----|----|------|----------------------|
|                                  | No.                       | L. | B. | D.   |                      |
| N.W. Maint of road from REO Road |                           |    |    |      |                      |
| to Shiv mandir main road         |                           |    |    |      |                      |
| Vai Mehta tola Ram tola          |                           |    |    |      |                      |
| Under main S.V (ce)              |                           |    |    |      |                      |
| Agency C.S Construction          |                           |    |    |      |                      |
| Agg No. 18. S.B.D 2016-17        |                           |    |    |      |                      |
| Date of start 24.08.2016         |                           |    |    |      |                      |
| A.D. Comp 25.7.23                |                           |    |    |      |                      |
| (11) Restoration of Rain         |                           |    |    |      |                      |
| Cuts — do —                      |                           |    |    |      |                      |
| 18x 2.0x 0.90x 0.30              |                           |    |    |      | 9.72m <sup>3</sup>   |
| 22x 3 x 0.80x 0.40               |                           |    |    |      | 21.12m <sup>3</sup>  |
| 20x 2.0x 0.30x 0.30              |                           |    |    |      | 3.60m <sup>3</sup>   |
| 23x 3.0x 1.0x 0.40               |                           |    |    |      | 27.60m <sup>3</sup>  |
|                                  |                           |    |    |      | 62.04                |
|                                  |                           |    |    | Unit | 62.04m <sup>3</sup>  |
| (212) Making up of Benty         |                           |    |    |      |                      |
| Shoulder (excess soil)           |                           |    |    |      |                      |
| — do —                           |                           |    |    |      |                      |
| 8x 3.0x 1.0                      |                           |    |    |      | 24.00m <sup>3</sup>  |
| 12x 3.0x 0.90                    |                           |    |    |      | 32.40m <sup>3</sup>  |
| 25x 3.0x 0.90                    |                           |    |    |      | 67.50m <sup>3</sup>  |
| 12x 2.0x 0.64                    |                           |    |    |      | 15.36m <sup>3</sup>  |
| 13x 3.0x 0.75                    |                           |    |    |      | 29.25m <sup>3</sup>  |
|                                  |                           |    |    |      | 168.51m <sup>3</sup> |
| (313) Patching up over           |                           |    |    |      |                      |
| bitumen surface                  |                           |    |    |      |                      |

Continuation

Continuation