

M.C.S.Y - 5 T

N.B.R - 96
Year - 2018 - 19

Schedule XLV-Form No. 134

5015 to Dhabia - tala.

DIVISION

SUB-DIVISION

Dabu Kumar Singh

Measurement Book

Blanks - Diamond shape.

5th Year Maintenance Bill

Abstract of cost : -
69

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work : - maintenance of P.V. from S.I.S to Dhabya Tola					
Agency : - Pappu Kumar Singh					
Agreement No.: - 60 SAP/2018-19					
Date of commencement : 09/03/2019					
Actual date of completion : 07/03/2020					
(1) 1 Restoration of Rains / Army width 20'1 morum - Ro - EI - 132.05 m ³ @ TMAP - (67) @ Rs. 380.58 /m ³ Rs. 50256.00 covering exceeding from the shoulder Ro - EI - 858.09 m ² @ TMAP - (68) @ Rs 57.33 /m ² Rs. - 49194.00					
(2) 3 Repair of POF hole filled with 75 mm CBM x 1.25 Ro - EI - 169.21 m ³ @ TMAP - (69) @ Rs. 366.27 /m ³ Rs. 61977.00					
(4) 5 patch repair of bituminous surface with conmix seal					

Continuation

C.O. RS = 161427.00

Sch. XLV-Form No. 134

B. F. Rs - 206014.00

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(10)					
(11) (iii)	Trimming of grass and weeds -				
	Do - EI -				
	13.85 m ² OUT MBP -	(67)			
	@ Rs. 2.18 /m ² Rs =	30.00			
(11)					
(12)	Painting on Poropel wall (Black & white strips) -	Do - EI -			
	61.07 m ² OUT MBP -	(67)			
	@ Rs. 108.98 /m ² Rs. 6655.00				
(12)					
(13)	Road marking with hot applied thermoset on Bituminous surface				
	289.97 m ² OUT MBP -	(67)			
	@ Rs. 8.50 /m ² Rs =	246744.00			
(13)					
(14)	Road marking with Hot Applied Thermoset on Concrete surface				
	Do - EI -				
	48.95 m ² OUT MBP -	(68)			
	@ Rs. 9.53 /m ² Rs. 46698.00				
	Total payable Rs. 506141.00				
(14) <u>Mr</u> <u>Day</u> <u>Copy</u> 0+3125 SE <u>appr</u> <u>10/10/14</u>					
Continuation					