

कार्यपालक अभियन्ता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमण्डल, बक्सर

पत्रांक.....435/

बक्सर, दिनांक.....20/3/25/

प्रेषक:-

कार्यपालक अभियन्ता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, बक्सर।

सेवा में,

नोडल पदाधिकारी,
3054 (M.R) कोषांग,
बिहार, पटना।

विषय:- शीर्ष 3054 नई अनुरक्षण नीति-2018 अंतर्गत Initial Rectification and Surface renewal. कराये गये कार्य हेतु अधियाचना के संबंध में।

महाशय,

उपर्युक्त विषयक कहना है कि विहित प्रपत्र में संलग्न विवरणी के अनुसार शीर्ष Mr 3054 New Maintenance Policy-2018. अन्तर्गत Initial Rectification and Surface renewal. कराये गये कार्य हेतु राशि की आवश्यकता है।

अतः कार्यहित में अनुरोध है कि उक्त अधियाचित राशि उपलब्ध कराने की कृपा की जाय ताकि कराये जा रहे कार्यों का विपत्र भुगतान किया जा सके।

- अनु०:- (1) अधियाचना प्रपत्र
(2) IRI Value Report
(3) Map
(4) प्रमाण-पत्र।

विश्वासभाजन

(Signature)

20.3.25

कार्यपालक अभियन्ता
ग्रा०का०वि०, कार्य प्रमण्डल,

बक्सर

(Signature)
20.3.25

FORM GFR 19-A

(See Government of India's Decision (I) below Rule- 150)
Form of Utilization Certificate upto date of 20.03.2025

Name of Scheme :- MR NEW MAINTENANCE POLICY-2018.

Sl. No.	Name of Scheme	Sanction No. & Date with Amount (Rs.In lacs)	Amount Received (Rs.In Lacs)	Particulars
Through C.F.M.S. Received			-	
1	MR NEW MAINTENANCE POLICY 2018.	BF up to 2024-2025 Lt No-02 dt-14.01.2025 <u>12524.36810</u>	12524.36810	Certified that Alltoment Received during the year 2024-2025 Throught C.F.M.S. Rs.12524.36810 lacs of grants-in- favour of Executive Engineer, R.W.D.(W) Division, Buxar. Bihar a sum of Rs.12501.25022 lacs has been utilized for the purpose of MR NEW MAINTENANCE POLICY-2018. schemes as given in the margin for which it was sanctioned and that the balance of Rs.23.11788 lacs remaining unutilized at the end of the period under report.
Total Rs. =			12524.36810	

- 2 Certified that I have satisfied myself that the conditions on which the grants- in - aid was sanctioned have been duly fulfilled. are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kind of Checks exercise:-

- i) Works have been supervised by Executive Engineer/ Superintending Engineer
- ii) Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer
- iii) Construction materials have been tested.
- iv) Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/ Executive Engineer.
- v) All other codal formalities have been observed.

3 **Physical progress achieved:-**

- i) Construction of Road works.
- ii) Construction of CD works.

D.A.O
R.W.D. (W) Division.
Buxar


20.3.25
Executive Engineer
R.W.D. (W) Division.
Buxar

20.3.25

Name of Division:- RWD Works Division Buxar.

Rural Works Department
MR NEW MAINTENANCE POLICY-2018. ALLOTMENT REQUISITION

Date-20.03.2025

Sl. No.	Year	Name of Road	Name of Contractor (In English)	Project Id	Administrative Sanction		Agreement Amount (In Lacs)	Value of IRJ (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Allotment Received (in Lacs)	Total Expenditure as per MIS (in Lacs)	Value of Measurement (in Lacs)	Current Demand (in Lacs)	Remarks	
73	2023-24	1047-Buxar Dansoi road to Ori (447)	Narendra Kumar	10401902115	1.300	56.01600	24.57359	7.44720	2057	25	5%	0.00000	0.00000	24.57359	24.57359	Physically complete

D.A.O
RWD Works Division
Buxar



20.3.25
Executive Engineer
RWD Works Division
Buxar
20.3.25

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, बक्सर


का0आ0स..... बक्सर/ दिनांक.....

कार्यालय आदेश


प्रमाणित किया जाता है कि बिहार ग्रामीण पथ अनुरक्षण नीती-2018 योजनान्तर्गत L047-Buxar Dansoi road to Ori (L47) पथ का कार्य गुणवत्ता एवं विशिष्टियों के अनुरूप पूर्ण कराया गया है। पथ के मापीपुस्त की जाँच मेरे द्वारा 10 प्रतिशत, सहायक अभियंता द्वारा 50 प्रतिशत एवं कनीय अभियंता के द्वारा शत प्रतिशत किया गया है।


20/03/2025

कनीय अभियंता
ग्रामीण कार्य विभाग
कार्य अवर प्रशाखा ईटाढ़ी


20.03.25

सहायक अभियंता
ग्रामीण कार्य विभाग
कार्य अवर प्रमंडल ईटाढ़ी


20.3.25

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, बक्सर

Name of Road:-L047-Buxar Dansoi road to Ori (L47) Contractor Name:-Narendra Kumar

Date	Time	Section	Length	Bumps	Speed	OR	IRI	ATEGORY	Latitude	Longitude	Event
19/3/25	14:58:28	No.	in km	in mm	Rate	mm/km	mm/km	ROAD			
19/3/25	15:04:15	57	0.1	200	10.1	2000	1880	G	25.51211	84.003654	Normal
19/3/25	15:05:28	57	0.1	210	20.2	2100	1962	G	25.51225	84.004314	Normal
19/3/25	15:06:48	57	0.1	210	20.2	2100	1962	G	25.5122	84.00465	Normal
19/3/25	15:08:01	57	0.1	260	20.2	2600	2370	G	25.51206	84.006452	Normal
19/3/25	15:09:08	57	0.1	210	10.1	2100	1962	G	25.51767	84.0074	Normal
19/3/25	15:10:25	57	0.1	230	10.1	2300	2125	G	25.51165	84.007967	Normal
19/3/25	15:12:02	57	0.1	110	10.1	2200	2044	G	25.51186	84.008125	Normal
19/3/25	15:12:51	57	0.1	210	10.1	2100	1962	G	25.512	84.008641	Normal
19/3/25	15:13:05	57	0.1	240	10.1	2400	1962	G	25.51195	84.009434	Normal
19/3/25	15:14:08	57	0.1	230	10.1	2300	2125	G	25.5119	84.00971	Normal
19/3/25	15:31:09	57	0.1	250	10.1	2500	2288	G	25.51192	84.009872	Normal
19/3/25	15:33:06	57	0.1	200	10.1	2000	1880	G	25.51181	84.010485	Normal
19/3/25		Length	1.300						25.51178	84.012146	Normal

$$Y = 0 * X^2 + 0.816 * X + 249$$

$$X = 2125$$

$$Y = 2044$$

(R) RURAL ROAD
Good Average Poor
<4000 4001-5000 >5001


IRI value=2057
Machine ID=19195

[Signature]
20/03/2025
AE

[Signature]
20/03/2025
AE

[Signature]
20/03/2025
EE

File: C:\Users\7SURYANAND MISHRA\Desktop\narendra\06031351.xlsx Section No. :57, Eqn :test
 Name of Customer :Narendra Kumar, Name of Work/ Road :L047- Buxar Dansoi road to Ori, Lab Job number :



CE
 20/03/2025
 JE

Prasad
 20.03.25
 JE

Pras
 20.3.25
 EE